

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, August 17, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. C0.4 boat launch sheen was observed.



2. C0.4 boat launch sheen was observed.



3. MP5.3 LDB tar globs and sheen observed.



4. MP5.63 LDB tar globs and sheen observed.



5. MP5.63 LDB tar globs and sheen observed.



6. Ceresco Dam sheen sweep observed operating.



7. MP4.5 below the former Island F area where sheen was observed.



8. MP4.5 below the former Island F sheen was observed when the boat reversed.



9. MP10.75 no sheen observed.



10. MP13.4 LDB no sheen observed.



11. MP15.5 RDB South Mill Pond no sheen observed.



12. MP8.4 LDB no sheen observed.



13. MP8.48 LDB no sheen observed.



14. MP21.5 Custer Drive Bridge no sheen observed.



15. MP27.0 RDB river bank erosion restoration work appeared completed.



16. MP26.25 RDB no sheen observed.



17. MP26.0 RDB no sheen observed.



18. MP24.75 LDB no sheen observed.




19. MP23.10 RDB no sheen observed.



20. MP21.5 Oxbow observed crew performing monthly sediment trap monitoring.



21. MP21.5 Oxbow observed crew performing monthly sediment trap monitoring.



22. Observed a sheen sweep boat operating between MP21.5 – MP28.0.



23. Morrow Lake sheen observed.



24. Morrow Lake sheen observed.