

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/09/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/04/2012 – 0700, 10/11/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • MP5.35 LDB, spontaneous ribbons of sheen observed along shoreline. • MP5.35 LDB, spontaneous sheen and tar globule observed along shoreline. • MP5.45 LDB, spontaneous sheen and tar globule observed along shoreline. • MP5.55 LDB, spontaneous sheen and tar globule observed along shoreline. • MP5.63 LDB no sheen observed. • Ceresco Dam Control Point observed the boom maintenance crew operating. • MP5.70 sheen observed within debris along Ceresco containment boom. • MP5.55 RDB spontaneous sheen observed. • MP19.25 Sediment Trap observed a sampling crew. • MP13.5 Overbank background sampling crew observed. • MP15.5 South Mill Pond no sheen observed. • MP15.55 LDB sheen observed, quantity of sheen would not warrant a sweep boat. • Morrow Lake South Cove sheen observed quantity of sheen would not warrant a sweep boat. • Morrow Lake Delta sheen observed along Gate E. • Morrow Lake Delta Gate C observed a crew performing curtain maintenance. • Morrow Lake Delta Gate B. • MP36.25 sheen observed, quantity of sheen would not warrant a sweep boat. 			
1630	Finish up inspections at E4 boat launch. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				