

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, January 25, 2013

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	N/A*	N/A*
C3.2 Water Gauge	N/A*	N/A*
E0.5 Water Gauge	N/A*	N/A*
E2 Water Gauge	N/A*	N/A*
E4 Water Gauge	N/A*	N/A*

* Water / Sediment Temperatures were unable to be collected due to ice formation along the river bank.

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. C0.4 Boat launch observed upstream river icing conditions.



2. C0.4 Boat launch observed downstream river icing conditions.



3. MP5.25 C0.4 observed river icing conditions.



4. Ceresco Dam impoundment observed river icing conditions.



5. Ceresco Dam impoundment observed river icing conditions.



6. MP5.9 Downstream from Ceresco Dam observed river conditions.



7. C3.2 Pole Barn observed core logging operations.



8. C3.2 Boat launch observed river icing conditions.



9. C3.2 Boat launch observed river icing conditions.



10. MP15.25 South Mill Pond observed river icing conditions.



11. MP15.25 South Mill Pond observed river icing conditions.



12. MP15.5 North Mill Pond observed river icing conditions.



13. MP19.25 observed river icing conditions.



14. MP21.5 observed river icing conditions.



15. E2 Boat launch observed river icing conditions.



16. MP27.0 E0.5 Boat launch observed river icing conditions.



17. MP27.0 E0.5 Boat launch observed river icing conditions.



18. Morrow Lake observed icing conditions.



19. Morrow Lake Neck/Morrow Lake Delta observed icing conditions.



20. Morrow Lake Delta observed icing conditions.



21. Morrow Lake Delta observed icing conditions.



22. MP21.25 RDB overbank oxbow observed the RI crew.