

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, February 20, 2013

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Source Area and Talmadge Creek overview.



2. Frac Tank City observed Cells A/B winterized.



3. MP3.75 observed river icing conditions.



4. Ceresco Dam impoundment river icing conditions.



5. Ceresco Dam impoundment river icing conditions.



6. MP10.4 RDB Sediment trap ice conditions.



7. MP10.5 LDB Sediment trap ice conditions.



8. MP10.75 Sediment Trap river icing conditions observed.



9. MP10.75 Sediment Trap river icing conditions observed.



10. MP11.78 Sediment trap.



11. MP14.75 Sediment trap.



12. Downstream end of the MP14.75 Sediment trap river icing conditions.



13. North and South Mill Pond river icing conditions.



14. MP19.25 Sediment trap.



15. MP19.25 Downstream end of the sediment trap. CSD buoy and sampler have been repositioned.



16. MP21.5 Sediment trap river icing conditions observed.



17. MP26.0 Sediment Trap river icing conditions observed.



18. MP28.25 Sediment trap. The can buoy on the upstream end of the sediment trap has been repositioned.



19. MP30.8 Sediment trap.



20. MP33.0 A Sediment trap.



21. MP33.0 B Sediment trap. The CSD sampler and buoy has been repositioned to its original location.



22. MP36.10 Sediment trap.



**23. Morrow Lake Delta A sediment trap.**



**24. Morrow Lake Delta overview.**



25. Morrow Lake Delta Neck observed the CSC buoy moving further into the neck towards the lake.



26. Morrow Lake Delta Neck buoy could not be located from the ground.



27. Morrow Lake icing conditions.



28. Morrow Lake icing conditions.