1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214
Kalamazoo River/Enbridge Spill	12/11/2012	1900	

4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
Containment Branch Recovery Team 1	**Name:**	Dan Capone & Joe Victory (START/US EPA)	**From:**	12/11/2012 0700
	Position:	Operations Section Chief	**To:**	12/11/2012 1830

7. Personnel Roster Assigned

Name	ICS Position	DUTY CELL
Dan Capone	Operations Section Chief	
Rex Johnson	Containment Branch Director	
Dan Zahner	Field Team Lead /CBR-4	

8. Activity Log

Activity Area	Ceresco, MP-19.25 LDB, MP-21.50 RDB, and MP 26.00 RDB Sediment Traps	**LAT Various** (DD.MMMM)	**LAT Various** (DD.MMMM)
OIL OBSERVED	**EXTENT OF OIL IMPACTED AREA**		
	DENSITY OF OIL /SHEEN		
Total Collection Points			
Total Boom Deployed			

Activity

Weston/START CBR 1 Team Activity:

Oversaw Enbridge Field Team 6 including Reed Rector (LBG) team lead for CSD sampling at sediment traps Ceresco, MP-19.25 LDB, MP-21.50 RDB, and MP 26.00 RDB.

Ceresco Sediment Trap

- C-02 – 82mm / 75mm
  - 1.3’ below water
- C-03 – 75mm / 107mm
  - 1.0’ below water

MP 19.25 RDB Sediment Trap

- C-01 – 20mm / -mm – LDB jar was broken, most likely from freezing water
  - 0.3’ above water
- C-02 – 61mm / 58mm
  - 0.1’ below water
- C-03 – 12mm / 10mm
  - 0.3’ above water
- C-04 – 70mm / 70mm
  - 0.5’ below water

	· C-05 – 50mm / 35mm o 1.2 – 1.1' below water slight tilt to RDB **MP 21.50 RDB Sediment Trap** · C-01 – 100mm / 115mm o 1.8-1.95' below water level tilt to RDB · C-02 – 67mm / 65mm o 2.0' below water level · C-03 – 50mm / 60mm o 1.2' below water level **MP 26.00 RDB Sediment Trap** · C-01 – 0mm / 0mm both jars broken o 0.5' above water · C-02 – 92mm / 88mm o 0.8' below water · C-03 – 0mm / 0mm RDB jar broken o On dry ground. LDB jar only had leaves and was not sampled. · C-04 – 65mm / 53mm o 1.3' to 1.5 feet below water, slight tilt to LDB · C-05 – 50mm / 25mm o 6.4' below water Broken sample jars came from CSDs that were above water, but had full jars from either higher water levels or rainwater. The tops appeared to freeze closed forming a "cap" on the jar, then the expanding water broke the bottom of the jar out. <u>Sampled</u> · SEKR2600C04S121112 · SEKR2600C05S121112 · SEKR2600C02S121112 Samples had a full 8oz jar. The rest of the Jars were removed from the CSDs and put in cold storage to be sampled tomorrow.
Health and Safety Issues	
Comments	Field notes are in CBR-4 Logbook