

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

<b>Facility Name :</b>	Bayou Chico Decon Area	<b>Facility Location ID:</b>	PD01
<b>Assessment Date :</b>	7/12/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	700 Myrick Street		
<b>City, State :</b>	Pensacola, FL	<b>County :</b>	Escambia

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	

**Additional Comments :**

ERM operated decon area contained only hard boom for decontamination. No oil contaminated waste for sampling on site during visit.

Grab samples of oil contaminated pom poms were collected in 4 32 oz. glass jars from roll-off #735-25 for purposes of running TCLP analysis for VOCs, SVOCs, metals and ignitability. It was thought at the time that the Obrien Response Management dock area might be the WM-Myrick staging area listed in the BP WMP. From information obtained later during the visit it was determined that this was not the WM-Myrick staging area. No undue concerns regarding waste management practices were noted during the visit.

Others present included:

Lance Trochessett, Obrien Response Management, Dock Master

US EPA ARCHIVE DOCUMENT