

US EPA ARCHIVE DOCUMENT

FINAL REPORT

Dam Safety Assessment of CCW Impoundments

James M. Barry Electric Generating Plant

**United States Environmental Protection Agency
Washington, DC**

December 8, 2010



O'BRIEN & GERE
www.obg.com

Dam Safety Assessment of CCW Impoundments

James M. Barry Electric Generating Plant

Prepared for:
US Environmental Protection Agency
Washington, DC



ROBERT R. BOWERS, P.E. – VICE PRESIDENT
O'BRIEN & GERE ENGINEERS, INC.



WILLIAM H. DIXON, P.E. – PROJECT ASSOCIATE
O'BRIEN & GERE ENGINEERS, INC.

TABLE OF CONTENTS

1. Introduction.....	1
1.1. General	1
1.2. Project Purpose and Scope	1
2. Project/Facility Description.....	2
2.1. Management Unit Identification.....	2
2.2. Hazard Potential Classification	3
2.3. Impounding Structure Details	3
2.3.1. Embankment Configuration.....	4
2.3.2. Type of Materials Impounded	4
2.3.3. Outlet Works.....	4
3. Records Review	5
3.1. Engineering Documents.....	6
3.1.1. Stormwater Inflows	8
3.1.2. Stability Analyses.....	8
3.1.3. Modifications from Original Construction	9
3.1.4. Instrumentation	9
3.2. Previous Inspections.....	10
3.3. Operator Interviews	12
4. Visual Inspection.....	14
4.1. General	14
4.2. Summary of Findings	14
5. Conclusions	15
6. Recommendations.....	16
6.1. Urgent Action Items.....	16
6.2. Long Term Improvement	16
6.3. Monitoring and Future Inspection	16
6.4. Time Frame for Completion of Repairs/Improvements.....	16
6.5. Certification Statement	17

Figures

Figure 1 –	Site Location Map
Figure 2 –	Site Layout
Figure 2A –	Photo Locations
Figure 2B –	Photo Locations
Figure 2C–	Photo Locations

Appendices

Appendix A – Visual Inspection Checklists
Appendix B – Photographs—Barry Ash Pond

1. INTRODUCTION

1.1. GENERAL

In response to the coal combustion waste (CCW) impoundment failure at the TVA/Kingston coal-fired electric generating station in December of 2008, the U. S. Environmental Protection Agency has initiated a nationwide program of structural integrity and safety assessments of coal combustion waste impoundments or “management units”.

A CCW management unit is defined as a surface impoundment or similar diked or bermed management unit or management units designated as landfills that receive liquid-borne material and are used for the storage or disposal of residuals or by-products from the combustion of coal, including, but not limited to, fly ash, bottom ash, boiler slag, or flue gas emission control residuals. Management units also include inactive impoundments that have not been formally closed in compliance with applicable federal or state closure/reclamation regulations.

The U.S. EPA has authorized O’Brien & Gere to provide actual site specific impoundment assessments at selected facilities. This project is being conducted in accordance with the terms of BPA#EP10W000673, Order No. EP-CALL-0001 dated June 14, 2010.

1.2. PROJECT PURPOSE AND SCOPE

The purpose of this work is to provide Dam Safety Assessment of CCW management units, including the following:

- Identify conditions that may adversely affect the structural stability and functionality of a management unit and its appurtenant structures
- Note the extent of deterioration, status of maintenance, and/or need for immediate repair
- Evaluate conformity with current design and construction practices
- Determine the hazard potential classification for units not currently classified by the management unit owner or by state or federal agencies

O’Brien & Gere’s scope of services for this project includes performing a site specific dam safety assessment of all CCW management units at the subject facility. Specifically, the scope includes the following tasks:

- Perform a review of pertinent records (prior inspections, engineering reports, drawings, etc.) made available at the time of the site visit to review previously documented conditions and safety issues and gain an understanding of the original design and modifications of the facility.
- Perform a site visit and visual inspection of each CCW management unit and complete the visual inspection checklist to document conditions observed.
- Perform an evaluation of the adequacy of the outlet works, structural stability, quality and adequacy of the management unit’s inspection, maintenance, and operations procedures.
- Identify critical infrastructure within 5 miles down gradient of management units.
- Evaluate the risks and effects of potential overtopping and evaluate effects of flood loading on the management units.
- Immediate notification of conditions requiring emergency or urgent corrective action.
- Identify all environmental permits issued for the management units
- Identify all leaks, spills, or releases of any kind from the management units within the last 5 years.

- Prepare a report summarizing the findings of the assessment, conclusions regarding the safety and structural integrity, recommendations for maintenance and corrective action, and other action items as appropriate.

This report addresses the above issues for the CCW Management Unit (the Barry Ash Pond or pond) at the James M. Barry Electric Generating Plant in Bucks, Alabama. The Barry Ash Pond is owned and operated by Alabama Power Company (Alabama Power), a subsidiary of the Southern Company. In the course of this assessment, O'Brien & Gere representatives obtained information from representatives of Alabama Power, the Southern Company, and the law firm of Balch & Bingham, LLP.

2. PROJECT/FACILITY DESCRIPTION

The James M. Barry Electric Generating Plant (Plant Barry) is located along the west bank of the Mobile River at 15300 U.S. Highway 43 North, Bucks, Alabama 36512, approximately 30 miles north of Mobile, Alabama, and is owned and operated by Alabama Power. A Site Location Map is included as Figure 1. Plant Barry is a seven unit electric generating facility, and it includes two, natural gas fired combined cycle units and five coal fire units with a total generating capacity of 2,657,200 KW. The five coal units produce approximately 400,000 tons of coal combustion waste (CCW) by-products per year, including bottom ash and fly ash. CCW that is produced during power generation is managed on-site with a single CCW management unit (Barry Ash Pond). Currently, only generating unit #5 at Plant Barry - the largest of the five coal-fired units - is equipped with a flue-gas desulphurization (FGD) scrubber, which helps to remove emissions such as sulphur dioxide and nitrous oxide.

A byproduct of the emission scrubbing process is synthetic gypsum, which is also currently disposed of in the Barry Ash Pond. Future plans call for the gypsum to be collected in a new Gypsum Collection Basin (GCB) currently under construction with an anticipated operational date of October 29, 2010. After the GCB is operational, the only gypsum byproduct disposed of in the Barry Ash Pond will be the decant water from the GCB.

This safety assessment report summarizes the July 7, 2010 inspection performed by the O'Brien & Gere team of the Barry Ash Pond management unit at Plant Barry.

2.1. MANAGEMENT UNIT IDENTIFICATION

The location of the Barry Ash Pond inspected during this safety assessment is identified on Figure 2 – Site Layout.

The Barry Ash Pond is located on the east to southeast side of the power plant. The pond area is bounded on the north by Plant Barry, on the east and south by the Mobile River. The southwest side of the Barry Ash Pond area is bounded by the Plant Barry cooling water discharge canal. The pond dam structure is not listed in the National Inventory of Dams (NID) database and therefore not rated. No federal or state agency regulates the Barry Ash Pond dam structure relative to the NID. Currently, there are no dam safety regulations in the State of Alabama.

The Barry Ash Pond was reportedly placed into service in 1965 and is approximately 600 acres in size. As of March 25, 2009, the total approximate ash storage capacity of the pond utilizing wet sluicing methods was estimated to be 9,623,753 cubic yards. At the same time the approximate volume of ash stored in the pond based on wet sluicing was estimated to be 6,305,645 cubic yards. As of December 2009, the approximate remaining available capacity based on wet sluicing was calculated to be 1,278,500 cubic yards. Using dry stacking operations, the approximate available capacity was calculated to be 8,000,000 cubic yards. These capacity estimates are based on surveys and calculations performed by Southern Company Services, a corporate affiliate of Alabama Power Company.

The pond is a diked impoundment formed by east, south and west embankments; the west and east embankments appear to tie into natural ground on the north side of the impoundment. The embankment has reportedly been modified four different times, in 1972, 1992, 1998, and 2004. Records of the 1972 and 1992 modifications were not available. In reviewing the literature, it was noted that the embankment was raised 3 feet in 1992. There have been no major modifications to the pond outfall structure. The pond was built on a marsh area and continues to support marsh-like wildlife, such as cat-tails, water hyacinths, alligators, swamp rats (nutria), and wild hogs.

According to documentation provided to USEPA by Alabama Power, CCW materials contained in the Barry Ash Pond include fly ash, boiler slag, flue gas emission control residuals, and other regulatory permitted low volume wastes, i.e., waste that is not hazardous for purposes of RCRA Subtitle C and is otherwise permitted under applicable regulations such as 40 C.F.R. §423.11. These materials, including storm water runoff from the Plant Barry, are transferred to the pond via the plant's storm water pump station.

Water flows from north to south through the pond and through two bridge openings in the diversion dike near the southeastern end of the pond, and, ultimately, into the outfall structure for discharge to the Mobile River. The riser portion of the concrete outfall structure is made up of a four-sided, 8-foot square overflow weir. The discharge conduit is a 48-inch diameter corrugated metal pipe (CMP). The outfall structure is protected by a timber debris barrier. The discharge is permitted under NPDES permit number AL0002879.

2.2. HAZARD POTENTIAL CLASSIFICATION

Currently, the State of Alabama does not have a Dam Safety law. Legislation under *HB 454: Alabama Dam Inventory and Classification Act* has been pending in the Alabama Legislature since February 2008. Should the State of Alabama implement the pending legislation into the law, the Barry Ash Pond would meet the definition of a regulated dam and be assigned a hazard classification. An opinion on potential hazard classification per the proposed Alabama legislation is beyond the scope of this report.

The definitions for the four hazard potentials (Less than Low, Low, Significant and High) to be used in this assessment are included in the EPA CCW checklist found in Appendix A. Based on the checklist definitions and as a result of this assessment, the hazard potential rating recommended for the Barry Ash Pond is **SIGNIFICANT**. The eastern embankment of the Barry Ash Pond is located adjacent to the Mobile River with the toe of slope of the embankment within approximately 100 feet of the edge of the river in some locations. A failure of embankments impounding the Barry Ash Pond could cause significant environmental damage if the CCW was released into the Mobile River thereby damaging the surrounding area, wildlife and habitat. The power station is located in a semi-rural area; therefore, damage to critical infrastructure or lifeline facilities in the event of a dam failure would likely be limited to the power plant facilities.

2.3. IMPOUNDING STRUCTURE DETAILS

The following sections summarize the structural components and basic operations of the Barry Ash Pond. A site plan showing the location of the pond on the plant property and its relevant features is shown on Figure 2. Also shown on Figure 2 is the approximate location of the Gypsum Collection Basin presently under construction. Note that Figure 2 was adapted from the available aerial imagery as noted and may not depict all of the present features and conditions. Additionally, photos taken of the Barry Ash Pond during the visual inspection are incorporated in a Photographic Log provided as Appendix B. The locations of the photos are shown on Figures 2A, 2B, 2C.

2.3.1. Embankment Configuration

The Barry Ash Pond is a diked earthen embankment structure that impounds an area of approximately 600 acres and has a capacity of approximately 9,623,753 cubic yards (5,965 acre-feet) according to the EPA ICR Response, dated March 26, 2009.

There is no indication or record of the pond being lined. The pond is divided into the main ash storage area and the decant area downstream of the diversion dike. Both areas are delineated on Figure 2. The crest of the main ash storage area, including the east and west embankments and the diversion dike, is at approximately elevation (EL) 24.5 feet above mean sea level. The south embankment elevation surrounding the decant area downstream of the diversion dike is at approximately EL 21.5 above mean sea level. The original pond bottom is at approximately EL 3.0 and the original dike side slopes before the 1998 raise and the construction of the diversion dike were approximately 3H:1V.

The embankment was originally constructed to a top elevation of approximately EL 18 feet above mean sea level. According to the *Plant Barry Ash Pond South Dike and Diversion Dike Slope Stability Report (September 2004)*, in 1992, the east and west embankments were raised three feet (approximate EL 21 feet above mean sea level) to obtain additional storage capacity. In 1998, the east and west embankment crest elevation was raised to between approximately EL 23 to EL 24.5 feet above mean sea level. A flow diversion dike was also constructed in 1999 near the south end of the pond to create a decant area prior to discharge through the outlet structure. The diversion dike crest elevation was constructed to approximately EL 18 feet above mean sea level. In 2004, the diversion dike crest elevation was raised to approximately EL 24.5 feet above mean sea level, and the crest of the south embankment was raised to approximately EL 21.5 feet above mean sea level. The side slopes were constructed at approximately 3H:1V.

There are no records or reports of major breaches or repairs to the structure. There have been minor repairs over the years such as filling of animal burrows, repairs to shallow slides, regular maintenance and mowing, stump removal at toe of slope, filling and compaction of surface erosion features, and placement of riprap along water's edge at south end of pond to help reduce wave action erosion.

There are no toe drains in the embankment. There is currently no operating instrumentation or monitoring piezometers.

2.3.2. Type of Materials Impounded

Influent into the Barry Ash Pond includes surface water runoff from Plant Barry, water with fly ash, bottom ash, boiler slag, flue gas emission control residuals, and other (regulatory permitted low volume wastes, i.e., waste that is not hazardous for purposes of RCRA Subtitle C and is otherwise permitted under applicable regulations such as 40 C.F.R. §423/11) wastes.

2.3.3. Outlet Works

The Barry Ash Pond is a diked impoundment that receives sluiced flows, plant storm water runoff, and direct precipitation. CCW enters the pond through the sluice pipes on the north end of the pond. The ash/water mixture travels through three separate cells in a "stream" where it begins the settling process. The flow path is shown on Figure 2. The ash settles out in the main part of the pond, and water is discharged to the decant area through the diversion dike where it flows to the pond outlet structure where it is discharged to the Mobile River. The pond outlet structure, located approximately near the center of the southern embankment of the impoundment, consists of a four-sided concrete weir riser box with a 48-inch CMP discharge barrel (See Appendix B - Photo B12 thru B16). The pond discharge to the Mobile River is permitted under ADEM NPDES

permit # AL0002879. There have been no reported major modifications to the outfall structure since it was originally constructed according to plant personnel and the *Plant Barry Ash Pond South Dike and Diversion Dike Slope Stability Report (September 2004)*.

3. RECORDS REVIEW

A review of the available records related to design, construction, operation and inspection of the Barry Ash Pond was performed as part of this assessment. The documents provided by Alabama Power, with their document designations, are listed below:

Table 3.1 *Summary of Barry Ash Pond Documents Reviewed*

Document	Dates	By	Description
BAR-API-0001	2010	Alabama Power	Aerial Photo of James M. Barry Electric Generating Plant, Aerial Photo of Barry Ash Pond, Aerial Photo of New Gypsum Collection Basin under Construction
BAR-API-0002	2010	Alabama Power	Aerial Photo/Topo of Barry Ash Pond
BAR-API-0003	Jan. 1998	Alabama Power	Alabama Power Plant Barry Report of Ash Pond Dike Proposed Modifications
BAR-API-0004	Sept. 2004	Alabama Power	Plant Barry Ash Pond South Dike and Diversion Dike Slope Stability Report
BAR-API-0005	June 16, 2010	Southern Company	Barry Steam Plant Ash Pond Dam – 2010 Dam Safety Inspection
BAR-API-0006	June 16, 2009	Southern Company	Barry Steam Plant Ash Pond Dam – 2009 Dam Safety Inspection
BAR-API-0007	Nov. 7, 2007	L.F. Dunlap & R.L. Mickwee	Barry Steam Plant Ash Pond Dam – Report of Biennial Dam Safety Inspection, November 7, 2007
BAR-API-0008	June 5, 1998	Synergy Earth Systems, Inc.	Summary Design Report – Existing Ash Pond Dike Impoundments, Barry Steam Plant – Bucks, Alabama
BAR-API-0009	Jan. 15, 2010	Alabama Department of Environmental Management	NPDES Permit No. AL0002879
BAR-API-0010	Oct. 1, 2009	Alabama Power	Barry Steam Plant – Ash Pond Visual Inspection Check List and Report Template
BAR-API-0011	Mar. 29, 2010	No Author Indicated	Barry Electric Generating Plant, BMP Site Plan, Figure 1
BAR-API-0012	Oct. 6, 2004	Southern Company Services, Inc.	Barry Steam Plant – Diversion Dike & South Main Dike Raise-Geologic Cross Sections & Typ. Dike Raise Sections
BAR-API-0013	Sept. 28, 2004	Southern Company Services, Inc.	Barry Steam Plant – Ash Pond Dike Raise-Geologic & Typical Dike Cross Sections
BAR-API-0014	Aug. 16, 1999	Southern Company Services, Inc.	Barry Ash Pond – Dike Extension-Phase 1 (1998) General Arrangement
BAR-API-0015	July 7, 1999	Southern Company Services, Inc.	Barry Steam Plant – Dike Crest Modifications-Sections West Side

Table 3.1 *Summary of Barry Ash Pond Documents Reviewed*

Document	Dates	By	Description
BAR-API-0016	July 7, 1999	Southern Company Services, Inc.	Barry Steam Plan – Dike Crest Modifications-Sections-East Side
BAR-API-0017	July 7, 1999	Southern Company Services, Inc.	Barry Steam Plant – Plans & Sections 1A & 5A
BAR-API-0018	Aug. 16, 1999	Southern Company Services, Inc.	Barry Ash Pond – Dike Extension-Phase 2 (1998) General Arrangement
BAR-API-0019	Nov. 17, 2004	Southern Company Services, Inc.	Plant Barry Ash Pond Discharge
BAR-API-0020	Mar. 25/Dec. 2009	Alabama Power	Estimate of Remaining Storage Capacity
BAR-API-0021	July 16, 2010	Southern Company Services, Inc.	Slope Stability Analysis of Main Ash Pond Dike
BAR-API-0022	June 29, 2009	Southern Company Services, Inc.	Safety Procedure for Dams and Dikes
BAR-API-0023	July 16, 2010	Southern Company Services, Inc.	Ash Pond Storm Event Hydraulic Capacity

3.1. ENGINEERING DOCUMENTS

Review of the design drawings, reports and calculations revealed information on the design details, construction chronology, and modifications of the Barry Ash Pond are summarized below.

- Original design drawings were not available; however, the Barry Ash Pond was reportedly placed into service in 1965.
- No information on an engineered pond liner system was noted in the records reviewed.
- No indication of former spills or releases of impounded materials from the Barry Ash Pond was noted in the records reviewed.
- A review of the *1998 Summary Design Report* prepared by Synergy Earth Systems, Inc. indicate that the earth fill of the original embankment section varied in soil type and consistency, but generally consists of a mixture of silty and sandy clays, clayey fine sands and sands underlain by a layer of soft organic silts and clays. According to the report, the underlying soils are the naturally existing marsh deposits over which the embankments were constructed.
- Southern Company issued a report on the stability of the Barry Ash Pond embankment structure in 1998 analyzing the effects of raising the crest of the embankment to increase the available storage of ash in the pond. Slope Stability Analysis results from the existing (1998) embankment cross-section indicated a minimum safety factor of 1.3 for a deep seated failure. The report recommended that the embankment be constructed on the upstream side against the existing slope and be raised no more than 3 feet at that time and constructed using a reinforcing grid. The report also recommended that fill material be tested to determine the most effective method of placement of the materials and that specifications be included in the final design to describe backfill materials, placement and compaction requirements, construction quality control measures, and monitoring of the construction activities.
- Record drawings for the 1998-99 embankment raise indicate that the typical section included a bottom layer of 2 to 3-feet deep of bottom ash placed on the inside slope of the existing embankment out to a point a minimum of 6-feet past the proposed new toe of slope. A double layer of Tensar Bx1200 geogrid 50% side lap (oriented perpendicular to centerline) extending to the proposed toe of slope was placed on top of the bottom ash. The existing embankment slope was double keyed with a layer of bottom ash placed on top of

the geogrid into the lower keyed section. A single layer of Tensar Ux1500HS geogrid was placed on the layer of bottom ash with the final lift of the embankment consisting of a clay layer keyed into the bottom ash and the existing embankment. The side slopes were constructed to 2H:1V. The top of the embankment was raised approximately 3 feet above the existing embankment.

- Design drawings provided as part of the 1998-99 embankment raise indicate that the diversion dike was also constructed in 1998-99.
- The 2004 Slope Stability Report referenced in Section 2.3.3 of this report was prepared in anticipation of raising the south main embankment and the diversion dike. The report indicated that the south main embankment could be raised 3 feet with a fly ash bolster, geogrid using bottom ash and clay fill with loads applied and still maintain a safety factor of 1.7. The diversion dike could be raised 4 feet with slopes laid back 4:1 with a 30 foot fly ash bolster on either side using a well compacted clay and still maintain a safety factor of 1.8. According to design drawings provided, construction of the south main embankment and the diversion dike would meet or exceed the specifications outlined above.
- As-built drawings were not provided in the records reviewed for the 2004 modifications.
- Southern Company prepared an *Ash Pond Storm Event Hydraulic Capacity*, dated July 16, 2010. This report was received from Alabama Power after the on-site inspection. The report concludes the following:

The ash pond has a present capacity of 414 acre-ft above the operating pool (Elev. 15 in the lower pond) using the July, 2009 topographical survey. The rainfall volume during 100-yr, 24-hour storm event is 204 acre-ft. Additional inflow to the pond from sluicing, plant storm water, and other sources, using maximum pump rates, is about 54 MGD. For the 24-hour event, the minimum freeboard is about 2.9 feet. During the critical 100-year, 2-hour storm, the minimum freeboard of the pond is 1.3 feet.

The report indicates that the conclusions are based on the following methodology:

The topography and layout of the ash pond was obtained from Drawing ES Topo-Plant Barry Ash Pond. Existing pond volumes were computed from the topography using AutoCad Civil 3D. The 100-year Intensity-Duration-Frequency Data for Plant Barry was obtained from the Rainfall Atlas of Alabama, published by the University of Alabama. The rainfall cases from 30 minutes to 24-hours were evaluated to determine the critical rain event. The critical rain event and the design 24-hour precipitation case were evaluated using the Rational Method to determine the peak level of stored water.

- Southern Company prepared a report entitled, *Slope Stability Analyses of Main Ash Pond Dike*, dated July 16, 2010. This report was received from Alabama Power after the on-site inspection. This analysis was performed to support the embankment modifications in 1998 and 2004. The analysis also addresses supplemental loading conditions, particularly earthquake seismic loading. A review of the report states that the slope stability computer model was run using the following assumptions and design criteria:
 - *According to the USGS earthquake acceleration probability maps for the vicinity of Plant Barry, the ground motion having a 2% probability of exceedance in 50 years is 0.06g.*
 - *The current required minimum criteria (factors of safety) were taken from the US Corps of Engineers Manual EM 1110-2-1902, October 2003.*
 - *The soil properties of unit weight, phi angle, and cohesion were obtained from historical laboratory results.*
 - *Soil stratigraphy and piezometric data was estimated from the historical boring logs*

According to the Summary of Conclusions presented in the report, the South Main Dike and the North East Main Dike factors of safety for various slope stability failure conditions under steady state and seismic conditions exceed the typical minimum factors of safety published in USACE Manual EM-1110-2-1902. The report concluded that *based on the results of these analyses all structures are stable.*

3.1.1. Stormwater Inflows

According to the *Ash Pond Storm Event Hydraulic Capacity Analysis* prepared by Southern Company, July 16, 2010 the Barry Ash Pond has a present capacity of 414 acre-ft above the operating pool (EL 15 in the lower pond i.e, the containment area south of the diversion dike) using the July 2009 topographical survey. It also states that the rainfall volume during the 100-year, 24-hour storm event is 204 acre-ft, and additional flow from sluicing, plant storm water runoff, and other sources, using maximum pump rates is about 54 MGD. The analysis states that for the 24-hour event, the minimum freeboard is about 2.9 feet, and during the 2-hour event the minimum freeboard is 1.3 feet. Based on this analysis, the Barry Ash Pond and the outlet structure have the capacity to contain and pass the design storm without overtopping the embankment.

3.1.2. Stability Analyses

Slope Stability Analyses were performed for existing and proposed conditions prior to the 1998 and 2004 embankment modifications. These reports concluded that the embankments would have adequate stability after the modifications.

As noted in Section 3.1 a report entitled, *Slope Stability Analysis of Main Ash Pond Dike*, dated July 16, 2010 was performed by Southern Company and provided to O'Brien & Gere after the July 7 site inspection. The slope stability analysis was performed to support the embankment modifications constructed in 1998 and 2004, and also provide additional analysis to address supplemental loading conditions, in particular earthquake seismic loading.

Slope stability was evaluated by preparing an embankment model and a static, steady-state stability analysis was performed using GeoStudio 2007 v 7.16, Build 4840 software for comparison to previously reported values from the 1998 and 2004 studies. No new field information was obtained for the preparation of the report. The soils information used in the analyses was obtained from information in the 1998 and 2004 reports.

The following table lists the factors of safety for various slope stability failure conditions.

South Main Dike		
Case	Computed Factor of Safety	Typical Minimum Factor of Safety
Barry South Main Dike Static Steady-State	1.5	1.5
Barry South Main Dike with Seismic	1.2	1.1
Barry South Main Dike Upstream Steady State	3.6	1.5
Barry South Main Dike Upstream with Seismic	1.5	1.1
Barry South Main Dike Full Pool	1.4	1.3
Barry South Main Dike Full Pool Upstream	3.5	1.3

North East Main Dike

Case	Computed Factor of Safety	Typical Minimum Factor of Safety
Barry North East Dike Static Steady-State	1.6	1.5
Barry North East Dike with Seismic	1.4	1.1
Barry North East Dike Upstream Steady State	6.4	1.5
Barry North East Dike Upstream with Seismic	3.6	1.1
Barry North East Dike Full Pool	1.6	1.3
Barry North East Dike Full Pool Upstream	11.7	1.3

Based on our review of the dike stability evaluation reports, the soil strength parameters were based on in-situ standard penetration tests, dilatometer tests, and cone penetration test data of the materials forming the dikes and natural foundation soils. Parameters for the new materials used to raise the dikes were based on laboratory testing and prior experience with similar materials. The soil strength parameters used in the slope stability analyses appear to have been conservatively estimated based on the lower bound results of the in-situ testing. The stability analysis methods appear to have been performed in general accordance with USACE Slope Stability Analysis Engineer Manual EM 1110-2-1902, and the computed factors of safety for the various loading conditions and dike sections analyzed appear to meet the minimums required by US Army Corps of Engineers for embankment dams.

3.1.3. Modifications from Original Construction

As noted above, the Barry Ash Pond has undergone modifications since its original construction. A review of the documentation provided indicates that Barry Ash Pond has undergone major modifications on four different occasions, 1972, 1992, 1998, and 2004. A summary of the available details from each modification follow:

- 1) 1972 – From the interview with plant personnel, it was learned that the embankment was raised slightly in 1972. No other information available concerning the 1972 modifications
- 2) 1992 – In 1992, the east and west embankments were raised 3 feet to obtain additional storage capacity.
- 3) 1998 – In 1998, the embankments were raised an additional four feet on the inboard side. The embankments were raised on the inboard due to outboard stability concerns and to avoid taking of wetlands. The internal raise sections were founded on existing deposited fly ash. During this modification, the diversion dike was also added to the pond. It was constructed on top of existing fly ash deposits using bottom ash as the dike fill. During the previous modifications, the south embankment was not raised.
- 4) 2004 – In 2004, the south main embankment and the diversion dike were raised. The south main embankment was raised approximately 3 feet and the diversion dike was raised approximately 4 feet. The cross-sections show that the material used to raise the diversion dike is a clay soil placed over the existing dike with a bolster of fly ash on both sides of the dike. The main south dike raise consisted of a clay fill material over a compacted bottom ash material placed on a fly ash bolster on the upstream side of the embankment.

3.1.4. Instrumentation

No instrumentation is present; however, there is a staff gauge which is read and recorded weekly by plant personnel.

3.2. PREVIOUS INSPECTIONS

As noted above in this report, there is not a Dam Safety Regulation in the State of Alabama. Alabama Power's parent company, Southern Company through its Hydro Services Group performs an annual inspection of the Barry Ash Pond. Records of the 2007, 2009, and 2010 inspections were provided for review. Prior to 2009, the inspections were performed on a biennial basis.

A summary of the 2009 inspection, performed on January 20, 2009 follows:

Main Ash Pond Dam – West Dike

- Full length of dam was inspected
- Shallow slides were noted in embankment at few locations, but not indicative of any kind of deep seated failure, although some tension cracks were observed near the dam crest. Similar areas have been repaired in past and seem to be performing well.
- Small nutria rat burrows observed on downstream face of dam and some locations show significant damage from 'rooting' activities by feral hogs
- Small seeps observed on west dike. Flow was not perceptible, and it did not appear that material was being removed from the dike, but it was observed that feral hog rooting was common in the small seep areas. Condition may be influenced by frequent and heavy rains experienced through December and January in State of Alabama

Main Ash Pond Dam - South Dike

- Many of same observations observed along western portion of dike were common along southern portion, but did not include any zones of seepage or significant damage from feral hogs.
- Crest observed to be in good condition except for one fairly sizable surface drainage rill along its interior or upstream side. Several smaller rills were also noted. Just east of outlet structure, a shallow slide was observed on downstream face of embankment.

Discharge Structure

- Inspected and observed to be in good condition

Main Ash Pond Dam – East Dike

- Crest and roadway generally observed to be in excellent condition
- Noted stumps from past clearing operations had been left in place near toe of slope
- Shallow slide observed on face of dike
- Notable surface drainage rills in portions of crest
- Feral hog activity and nutria rat burrows observed.

The Southern Company Hydro Services Group recommendations resulting from 2009 Inspection included the following:

1. Continue regular maintenance and mowing of embankment slopes
2. Conduct inspections of the ash pond dam at least weekly, with close observation of the dam toe by walking once per month
3. Fill in any nutria rat burrows with concrete or flowable fill material and repair any areas damaged by feral hog wallowing or rooting
4. Repair shallow slides along embankment face as time and budgeting allow. The first area that the inspection recommends be repaired is located near the midpoint of the eastern portion of the dam

5. The removal of stumps along the dam toe is recommended. Any stump removal must be performed conscientiously to prevent damage to the embankment structure, and any resulting holes should be refilled with compacted soil fill.
6. Repair the two noted surface drainage erosion features noted on the crest of the dam south and east dikes with compacted soil fill and re-vegetate.
7. Pay close attention to area of seepage along west dike. Any detrimental changes to seepage flow and/or any indications of materials being removed from the dike by flow should be reported to SCG Hydro Services immediately

The report from the 2010 inspection (June 16, 2010) indicates that all items recommended for maintenance and/or repair in the 2009 inspection were completed satisfactorily. A summary of the 2010 inspections follows:

Main Ash Pond Dam – West Dike

- Full length of dam was inspected
- Roadway along crest appeared to be in excellent condition
- Portion of embankment adjacent to bridge crossing canal recently repaired
- Vegetation is well maintained and mowed
- Nutria rat burrows observed, but far less than in 2009
- Several zones of soil cracking (15 feet to 100 feet long) were observed adjacent to downstream edge of the crest. These cracks historically have been indicators of future shallow slope slides or slumps. This condition is not seen as a credible threat to dam safety, but the cracks are a long-term and recurring maintenance item for plant staff once slide occurs.

Main Ash Pond Dam – South Dike and Discharge Structure

- Full length of dam was inspected
- Generally in good condition, suitably vegetated, and adequately mowed
- Some scour on upstream face on the western side of the south dike – most likely due to increased water velocities in this area
- Vegetation observed near interface between embankment and the ash pond waterline
- Discharge Structure observed to be in good condition

Main Ash Pond Dam – East Dike

- Full length of dam was inspected
- Vegetation was adequate and well maintained
- Crest and roadway generally noted to be in excellent condition
- Soil cracking along crest of dam, but to lesser extent than on West Dike
- Small surficial slides
- Feral activity, or rooting noted, but to lesser extent than in 2009 inspection

Diversion Dike

- Appeared to be performing adequately
- No signs of excessive erosion or settlement
- Old wooden plank bridges noted during 2009 inspection have been replaced with concrete bridges

The Southern Company Hydro Services Group recommendations resulting from 2010 inspection were as follows:

No.	Description	Location
1	Continue regular maintenance and mowing of embankment slopes	All Earth Embankment Structures
2	Burrows and /or areas of feral hog disturbance be repaired as they are located	All Earth Embankment Structures
3	When shallow slides on the embankment occur, the disturbed areas are should be repaired, revegetated, and protected with erosion protection material (such as Geomat or similar product). It is noted that in past slope repairs the plant has elected to flatten the slope somewhat, and it is recommended that this practice continue.	All Earth Embankment Structures (most common on East and West Dike)
4	It is recommended that the upstream portion of the South Dike embankment disturbed by scour be armored against erosion by the replacement of rip-rap. Alternatively, the upstream crest could be repaired by grading and revegetating.	All Earth Embankment Structures
5	The removal of stumps along the South Dike embankment toe is recommended. Any stump removal must be performed conscientiously to prevent damage to the embankment structure, and any resulting holes should be refilled with compacted soil fill.	South Dike
6	Vegetation in the lower portion of the pond where water is on the embankment should be removed so the interface can clearly be observed	South Dike

It is noted that during O'Brien & Gere's July 7, 2010 that Item 4 had been implemented. The other items are ongoing maintenance items, and based on our interview with the plant staff, these items are being implemented as needed.

3.3. OPERATOR INTERVIEWS

Numerous plant and corporate personnel took part in the inspection proceedings. The following is a list of participants for the inspection of the Barry Ash Pond:

Table 4 *List of Participants*

Name	Affiliation	Title
Gerrad Wilson	Southern Company	Engineer II/Earth Science & Environmental Engineering
Clifton Bennett	Alabama Power	Security Team Leader/Plant Barry
Rick Anderson	Alabama Power	Compliance & Support Manager/Plant Barry
Charleen Sikes	Alabama Power	TL-Compliance/Plant Barry
Dana Pizarro, PE	O'Brien & Gere Engineers, Inc.	Senior Managing Engineer
Billy Dixon, PE	O'Brien & Gere Engineers, Inc.	Project Associate
Tommy Ryals	Alabama Power	Environmental Affairs Supervisor
Stan Connally	Alabama Power	Plant Manager/Plant Barry
Jim Pegues, PE	Southern Company	Principal Engineer/Earth Science & Environmental Engineering
Steve Burns	Balch & Bingham, LLP	Attorney

Facility personnel provided a good working knowledge of both the Barry Ash Pond, provided general plant operation background and provided requested historical documentation. In addition to the facility personnel (Alabama Power), Engineers from Southern Company (Owner of Alabama Power) were present to provide additional information from previous impoundment inspections. Also present was legal counsel representing Southern Company and Alabama Power. These personnel also accompanied O'Brien & Gere throughout the visual inspections to answer questions and to provide additional information as needed in the field.

A summary of the interview follows:

- No known spills or releases of impounded materials from the Barry Ash Pond have occurred.
- There is no indication of major seepage
- An annual inspection is performed by Southern Company's Hydro Services Group
- Weekly top of dam inspections are performed by Plant Barry staff
- Monthly top of dam inspections are performed by Plant Barry staff
- If minor deficiencies are noted during inspections, plant staff work to make repairs immediately
- The plant has dedicated materials for embankment repairs stockpiled north of cell 1 area .
- Major deficiencies are brought immediately to the attention of plant management for resolution.
- Hydro Services Group provides formal dam inspection training to Plant Barry staff
- No major modifications to outfall structure
- There are no design drawings available for the original embankment structure
- There have been minor repairs over the years such as filling in minor rutting, animal burrows, removal of stumps, but no major repairs have been required.
- Plant Barry is owned and operated by Alabama Power. Alabama Power is a subsidiary of Southern Company
- Plant Barry has written Emergency Response Plan and Spill Prevention Control and Countermeasure Plan
- The embankment has no toe drains
- Major modifications to the embankments were performed in 1998-99 and 2004-2005 consisting of raising the embankment height 4 feet and 3 feet, respectively.

4. VISUAL INSPECTION

The following sections summarize the inspection of the Barry Ash Pond, which occurred on July 7, 2010. Following the inspection, O'Brien & Gere completed the EPA inspection checklists for the Pond, which was submitted electronically to EPA on July 12, 2010. A copy of the completed inspection checklist is included as Appendix A.

4.1. GENERAL

The weather on the dates of the inspection was partly cloudy, humid and approximately 91 degrees. The visual inspection consisted of a thorough site walk along the entire perimeter of the Barry Ash Pond as well as along the entire length of the diversion dike. O'Brien & Gere team members walked the crest and outward toe of the embankment, and made observations along the toe, outboard slope, and crest of the embankment, and along exposed portions of the inboard slopes. We also observed the inlet/outlet structures and current operation. At the time of the inspection, O'Brien & Gere completed an EPA inspection checklist which was submitted electronically to EPA on July 12, 2010. A copy of the completed checklist is included in Appendix A.

Although not part of the inspection, the O'Brien & Gere team also observed the Gypsum Collection Basin currently under construction.

Photos of relevant features and conditions observed during the inspection were taken by O'Brien & Gere and are provided in Appendix B for the Barry Ash Pond. A Site Plan of the Barry Ash Pond is presented as Figure 2. Figures 2A, 2B, and 2C provide photograph locations and directions.

4.2. SUMMARY OF FINDINGS

The following observations were made during the inspection:

- Sluiced CCW by-product discharge enters the pond near the northeast corner and is routed to the southeast end of the pond through three separate cells where it begins the settling process (Appendix B – Photo B33).
- Water flowing out of the final cell into the main body of the ash pond continues to flow southeastward (Appendix B – Photo B34) towards a diversion dike (Appendix B – Photos B27, B28 and B29) where it is decanted over one or two concrete outfall weir structures (Appendix B – Photos B26 and B30) into the ash pond decant/discharge pool and eventually through the outlet structure to the Mobile River (Appendix B – Photo B12 and B16). The primary outfall weir is positioned at a lower elevation, and the only flow observed during the inspection was a discharge of clear water through the primary outfall. There was no flow through the secondary outfall.
- The outboard slope is well vegetated and appears well maintained and had been mowed prior to the inspection. Previous removal of brush and trees from the outboard slope was evident in the form of stumps and roots. The crest of the embankment is well maintained with a stone surface and is also used as a roadway completely encircling the ash pond (Appendix B – Photo B5). Recently completed repairs of minor sloughing and from the removal of a temporary mound placed for drilling were observed on the east embankment.
- Standing water/wetlands was observed against downstream toe for significant portions of the embankment on the east side of the pond. Water does not appear to result from any seepage. No discoloration or sediment is apparent.
- A few small animal burrows were noted on the outboard slopes of the eastern embankments due mainly to feral hogs and nutria swamp rats (Appendix B – Photo B3)

- There is some minor surficial sloughing at numerous locations and some bulging at locations where recent embankment raising meets previous embankment, but no cracks or scarps were observed in these areas (Appendix B – Photo B5).
- Approximately 5-7 trees on downstream embankment just up from toe of slope near stabilized portion of pond on Northwest end (Appendix B – Photo B23).
- The outlet structure appeared to be in good condition and functioning normally (Appendix B – Photos B12 and B16). Flow over the discharge weirs appeared clear.

5. CONCLUSIONS

Based on the ratings defined in the BPA Task Order Performance Work Statement (Satisfactory, Fair, Poor and Unsatisfactory), the information reviewed and the visual inspection, the overall condition of the Barry Ash Pond is considered to be **SATISFACTORY**. Acceptable performance is expected under all loading conditions.

The owner has implemented regular inspections and maintenance which enable the impoundment to be kept in good working order.

Our interviews with plant engineering personnel responsible for the operation of the impoundment indicate that a regular operations plan (*Safety Procedure for Dams and Dikes* prepared by Southern Company) is in use at the Barry Ash Pond facility. Since 1998, any modifications to the existing embankments have been supported with engineering analyses to ensure that such modifications will not impact the stability of the embankment. The regular operating procedures of the facility do not appear to be impacting the structural integrity of the impounding embankments.

The plant engineering staff maintain all design documents and inspection reports in a well organized manner. Plant personnel participated and cooperated with this inspection and provided all information requested. The plant operations personnel have received training in dam safety inspections and currently perform weekly inspections of the embankment with monthly inspections of the toe of the embankment. The Southern Company Hydro Services Group performs a yearly inspection and publishes a detailed inspection report containing findings and recommendations for the Plant Barry management. Based on these findings, we are of the opinion that the operations and maintenance procedures being practiced at the Barry Ash Pond are adequate, provided that recommended maintenance items identified in the most recent Southern Company Hydro Services Group inspection are carried out.

6. RECOMMENDATIONS

Based on the findings of our visual inspection and review of the available records for the Barry Ash Pond, O'Brien & Gere recommends that Plant Barry continue with the inspection and maintenance program in place, and additional maintenance of the embankments be performed to correct the miscellaneous deficiencies cited in the most recent Southern Company Hydro Services Group inspection.

6.1. URGENT ACTION ITEMS

None of the recommendations are considered to be urgent, since the issues noted above do not appear to threaten the structural integrity of the dam in the near term.

6.2. LONG TERM IMPROVEMENT

The deficient conditions observed during the inspection do not require immediate attention, but should be addressed in the near future as part of a regular maintenance plan.

6.3. MONITORING AND FUTURE INSPECTION

O'Brien & Gere recommends continued participation in annual inspections performed by Southern Company's Hydro Services Group as well as the weekly and monthly inspections performed by Plant Barry personnel. Since standing water from the river and wetlands in East Dike area make it difficult to assess whether or not seepage is coming from the dam, we recommend that the inspector(s) pay special attention when performing the monthly toe of slope inspections in this area to look for sediment in the water or discoloration that may indicate a potential for loss of embankment material. O'Brien & Gere also recommends that the inspection procedures in the Southern Company's *Safety Procedure for Dams and Dikes* continue to be followed, and that the document be updated as new Federal, State and Local rules and regulations are implemented.

6.4. TIME FRAME FOR COMPLETION OF REPAIRS/IMPROVEMENTS

Based on our conversations with representatives of Alabama Power the maintenance/repair items noted above are currently underway and being implemented without delay. We recommend that the owner continue toward this schedule as planned.

6.5. CERTIFICATION STATEMENT

I acknowledge that the Barry Ash Pond CCW management unit referenced herein was personally inspected by me on July 7, 2010 and was found to be in the following condition:

SATISFACTORY

FAIR

POOR

UNSATISFACTORY

Signature: _____



William H. Dixon
AL PE # 30128

Date: _____

12/8/2010


FIGURE 1



ADAPTED FROM: CREOLA QUADRANGLE, AL U.S.G.S. 7.5 MIN. QUAD 1985
 MOUNT VERNON QUADRANGLE, AL U.S.G.S. 7.5 MIN. QUAD 1982
 STIGGINS LAKE QUADRANGLE, AL U.S.G.S. 7.5 MIN. QUAD 1983
 THE BASIN QUADRANGLE, AL U.S.G.S. 7.5 MIN. QUAD 1985



US EPA
 DAM SAFETY ASSESSMENT
 OF CCW IMPOUNDMENTS
 BARRY ASH POND
 BUCKS, ALABAMA
 SITE LOCATION MAP



13498/46122
 December 2010




FIGURE 2



NOTE
Aerial imagery provided by National Agriculture Imagery Program (USDA), 2009.

JAMES M. BARRY
ELECTRIC GENERATING PLANT
BARRY ASH POND
BUCKS, ALABAMA

SITE LAYOUT



DECEMBER 2010
13498/46122



OBRIEN & GERE



FIGURE 2A




NOTE
Aerial imagery provided by National Agriculture Imagery Program (USDA), 2009.

LEGEND

 B1 Photograph Direction/Location

JAMES M. BARRY
ELECTRIC GENERATING PLANT
BARRY ASH POND
BUCKS, ALABAMA

PHOTO LOCATIONS



DECEMBER 2010
13498/46122



OBRIEN & GERE



FIGURE 2B




NOTE
Aerial imagery provided by National Agriculture Imagery Program (USDA), 2009.

LEGEND

 Photograph Direction/Location

JAMES M. BARRY
ELECTRIC GENERATING PLANT
BARRY ASH POND
BUCKS, ALABAMA

PHOTO LOCATIONS



DECEMBER 2010
13498/46122



OBRIEN & GERE



FIGURE 2C




NOTE
Aerial imagery provided by National Agriculture
Imagery Program (USDA), 2009.

LEGEND

 Photograph Direction/Location

JAMES M. BARRY
ELECTRIC GENERATING PLANT
BARRY ASH POND
BUCKS, ALABAMA

PHOTO LOCATIONS



DECEMBER 2010
13498/46122



OBRIEN & GERE



This document was developed in color. Reproduction in B/W may not represent the data as intended.

FIGURE 2D




NOTE
Aerial imagery provided by National Agriculture Imagery Program (USDA), 2009.

LEGEND

C1 Photograph Direction/Location

JAMES M. BARRY
ELECTRIC GENERATING PLANT
BARRY ASH POND
BUCKS, ALABAMA

PHOTO LOCATIONS



DECEMBER 2010
13498/46122



O'BRIEN & GERE

Visual Inspection Checklists



Site Name: James M. Barry Electric Generating Plant	Date: July 7, 2010
Unit Name: Plant Barry	Operator's Name: Alabama Power Company
Unit I.D.: Barry Ash Pond	Hazard Potential Classification: High Significant Low
Inspector's Name: William Dixon/Dana Pizarro	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?	Annual		18. Sloughing or bulging on slopes?	✓	
2. Pool elevation (operator records)?	See Note		19. Major erosion or slope deterioration?		✓
3. Decant inlet elevation (operator records)?	See Note		20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?	N/A		Is water entering inlet, but not exiting outlet?		✓
5. Lowest dam crest elevation (operator records)?	See Note		Is water exiting outlet, but not entering inlet?		✓
6. If instrumentation is present, are readings recorded (operator records)?	✓		Is water exiting outlet flowing clear?	✓	
7. Is the embankment currently under construction?		✓	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	See Note		From underdrain?		✓
9. Trees growing on embankment? (If so, indicate largest diameter below)	✓		At isolated points on embankment slopes?		✓
10. Cracks or scarps on crest?		✓	At natural hillside in the embankment area?		✓
11. Is there significant settlement along the crest?		✓	Over widespread areas?		✓
12. Are decant trashracks clear and in place?	✓		From downstream foundation area?		✓
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		✓	"Boils" beneath stream or ponded water?		✓
14. Clogged spillways, groin or diversion ditches?		✓	Around the outside of the decant pipe?		✓
15. Are spillway or ditch linings deteriorated?		✓	22. Surface movements in valley bottom or on hillside?		✓
16. Are outlets of decant or underdrains blocked?		✓	23. Water against downstream toe?	✓	
17. Cracks or scarps on slopes?		✓	24. Were Photos taken during the dam inspection?	✓	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #	Comments
2.	Records available - staff gauge reading two times per month.
3.	Alabama Power to measure; will be provided with report.
5.	Embankment height ranges from 19 to 20 feet high, cross-sections will be provided in report.
8.	No information available for foundation preparation.
9.	Approximately 5 - 7 trees on downstream embankment just up from toe of slope near stabilized portion of pond on NW end. Other trees near toe at numerous other locations.
18.	Sloughing - minor surficial sloughing at numerous locations; bulging at some locations where recent embankment raising meets previous embankment, but no cracks or scarps observed in these areas.
23.	Standing water/wetlands against downstream toe for significant portions of embankment. Water does not appear to result from any seepage. No discoloration or sediment apparent.

U. S. Environmental Protection Agency



Coal Combustion Waste (CCW)
Impoundment Inspection

Impoundment NPDES Permit # AL0002879 INSPECTOR William Dixon/ Dana Pizarro
Date 7/07/2010

Impoundment Name Barry Ash Pond
Impoundment Company Alabama Power Company
EPA Region 4
State Agency (Field Office) Address Alabama Dept. of Economic & Community Affairs
Office of Water Resources
Montgomery, AL

Name of Impoundment : (Report each impoundment on a separate form under the same
Impoundment NPDES
Permit number)

New _____ Update _____

Is impoundment currently under construction?	Yes _____	No <u>X</u>
Is water or ccw currently being pumped into the impoundment?	<u>X</u>	_____

IMPOUNDMENT FUNCTION: receives and stores sluiced fly ash, boiler slag, flue
gas emission control residuals, and gypsum residuals

Nearest Downstream Town : Name Creola, AL
Distance from the impoundment Approximately 11 miles
Impoundment

Location: Longitude 87 Degrees 59 Minutes 44 Seconds
Latitude 31 Degrees 00 Minutes 01 Seconds
State AL County Mobile County, AL

Does a state agency regulate this impoundment? YES _____ NO X

If So Which State Agency? _____


_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

X SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

Environmental damage to Mobile River. Failure would cause shutdown of power plant.

CONFIGURATION:



☐ Cross-Valley

☐ Side-Hill

☒ Diked

☐ Incised (form completion optional) ☐ Combination Incised/Diked

Embankment Height 19 to 20 feet Embankment Material Sandy clay

Pool Area 597 acres Liner None

TYPE OF OUTLET (Mark all that apply)

 Open Channel Spillway

 Trapezoidal

 Triangular

 Rectangular

 Irregular

 depth

 bottom (or average) width

 top width

 X **Outlet**

 inside diameter (No
drawings available; Alabama
Power to measure)

Material

 X corrugated metal


 welded steel

 concrete


 plastic (hdpe, pvc, etc.)

 other (specify)


TRAPEZOIDAL





TRIANGULAR



RECTANGULAR



IRREGULAR



Is water flowing through the outlet? YES X NO

 No Outlet

 X **Other Type of Outlet** (specify) Decanting tower with weir and debris barrier

The Impoundment was Designed By No information available

Has there ever been a failure at this site? YES _____ NO X

If So When? _____

If So Please Describe : _____

[illegible]

Has there ever been significant seepages at this site? YES _____ NO X

If So When? _____

IF So Please Describe: _____

US EPA ARCHIVE DOCUMENT

Has there ever been any measures undertaken to monitor/lower Phreatic water table levels based on past seepages or breaches at this site? YES _____ NO X

If so, which method (e.g., piezometers, gw pumping,...)? _____

If so Please Describe : _____

US EPA ARCHIVE DOCUMENT

Photographs – Barry Ash Pond

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
Northeast

Description:
Looking
northeast along
north section of
the east
embankment –
Note where top
of embankment
was raised on
right side of
photo resulting
from 1998
Study

Date: 7/7/2010

Photo Number:
B1

Photographer:
WHD/DRP



Orientation:
Northeast

Description:

Animal rutting
near toe of east
embankment

Date:
7/7/2010

Photo Number:
B2

Photographer:
WHD/DRP



PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
Southeast

Description:

Mound built up for drill rig to take soil borings. During January 1998 soils investigation for proposed ash pond dike modifications



Date:
7/7/2010

Photo Number:
B3

Photographer:

WHD/DRP

Orientation:
Southeast

Description:

Looking southeast along top of east embankment on north side of CCW Management Unit – Note where top of embankment was raised on right side of photo resulting from 1998 Study



Date:
7/7/2010

Photo Number:
B4

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
Southeast

Description:

Repair area on side slope at area where mound was built up to take soil borings in 1998 soils investigation



Date:
7/7/2010

Photo Number:
B5

Photographer:
WHD/DRP

Orientation:
East

Description:
Repair area near outward toe of east embankment slope on east side of CCW Management Unit



Date:
7/7/2010

Photo Number:
B6

Photographer:
WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
South

Description:
Looking south
along east
embankment.
Diversion Dike
is seen breaking
off to the right
(west) in the
photo.



Date:
7/7/2010

Photo Number:
B7

Photographer:
WHD/DRP

Orientation:
West

Description:

Looking west
towards
southern
portion of
embankment



Date:
7/7/2010

Photo Number:
B8

Photographer:
WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant

Location: Bucks, Alabama

Orientation:

Northwest

Description:

Overflow
Discharge
Structure



Date:

7/7/2010

Photo Number:

B9

Photographer:

WHD/DRP

Orientation:

N/A

Description:

Looking down
into overflow
discharge
structure – 8-
foot square
with four
overflow weirs



Date:

7/7/2010

Photo Number:

B10

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:

West

Description:

Gabion support on north side of south portion of embankment between embankment and discharge access structure



Date:

7/7/2010

Photo Number:

B11

Photographer:


WHD/DRP

Orientation:

South

Description:

Access structure to 48-inch discharge pipe



Date:

7/7/2010

Photo Number:

B12

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:

West

Description:

Looking west at access structure to discharge pipe – Note 48-inch discharge pipe underneath access structure



Date:

7/7/2010

Photo Number:

B13

Photographer:

WHD/DRP

Orientation:

East

Description:

Looking east along south embankment towards Discharge Structure. Note rip rap protection added on inbound slope for wave protection



Date:

7/7/2010

Photo Number:

B14

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:

Northwest

Description:

Looking
northwest along
south
embankment
towards Plant
Barry



Date:

7/7/2010

Photo Number:

B15

Photographer:

WHD/DRP

Orientation:

Northwest

Description:

Looking
northwest along
south
embankment
towards Plant
Barry



Date:

7/7/2010

Photo Number:

B16

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:

Northwest

Description:

Looking northwest along south embankment towards Plant Barry – Note closed and stabilized portion of embankment on right side of road



Date:

7/7/2010

Photo Number:

B17

Photographer:

WHD/DRP

Orientation:

Northwest

Description:

Trees near toe of outward slope of south embankment. This portion of embankment is in area where CCW Management Unit has been closed and stabilized



Date:

7/7/2010

Photo Number:

B18

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant Ash Pond

Location: Bucks, Alabama

Orientation:
Southwest

Description:

Diversion Dike
Sign near
intersection of
main
embankment
and diversion
dike on east
side of CCW
Management
Unit



7/7/2010

Photo Number:
B19

Photographer:
WHD/DRP

Orientation:
Northeast

Diversion Dike
sign near
intersection of
east
embankment
and diversion
dike on west
side of CCW
Management
Unit



Date:
7/7/2010

Photo Number:
B20

Photographer:
WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:

Northwest

Description:

Looking
northwest from
Bridge over
Primary
Diversion Dike
Outfall near
west end of
Diversion Dike



Date:

7/7/2010

Photo Number:

B21

Photographer:

WHD/DRP

Orientation:

West

Description:

Looking west
along Diversion
Dike towards
Primary
Diversion Dike
Outfall



Date:

7/7/2010

Photo Number:

B22

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant

Location: Bucks, Alabama

Orientation:

East

Description:

Looking east
along Diversion
Dike from
Primary
Diversion Dike
Outfall – Note
rutting from
machinery on
right side of
photo



Date:

7/7/2010

Photo Number:

B23

Photographer:

WHD/DRP

Orientation:

Northeast

Description:

Northwest side
of Secondary
Diversion Dike
Outfall



Date:

7/7/2010

Photo Number:

B24

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
Northeast

Description:
Looking at
southeast side
of Secondary
Diversion Dike
outfall



Date:
7/7/2010

Photo Number:
B25

Photographer:
WHD/DRP

Orientation:
Southwest

Description:
Looking
southwest
along Diversion
Dike towards
Secondary
Diversion Dike
Outfall near
east end of
Diversion Dike



Date:
7/7/2010

Photo Number:
B26

Photographer:
WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
Northeast

Description:
Discharge lines
Plant Barry into
CCW
Management
Unit



Date:
7/7/2010

Photo Number:
B27

Photographer:
WHD/DRP

Orientation:
Southwest

Description:
Looking
towards Cell #1
into CCW
Management
Unit



Date:
7/7/2010

Photo Number:
B28

Photographer:
WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:
South

Description:

Discharge
piping into
stormwater
pumping station



Date:

7/7/2010

Photo Number:

B29

Photographer:

WHD/DRP

Orientation:

West

Description:

Stormwater
Pumping
Station



Date:

7/7/2010

Photo Number:

B30

Photographer:

WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Barry Ash Pond

Location: Bucks, Alabama

Orientation:

North east

Description:

Emergency
Repair
Materials



Date:

7/7/2010

Photo Number:

B31

Photographer:

WHD/DRP

Photographs – Gypsum Collection Basin

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Gypsum Basin

Location: Bucks, Alabama

Orientation:
Northeast

Description:
Gypsum
Collection Basin
Area –
Emergency
Slurry Pond
Pumps



Date:
7/7/2010

Photo Number:
C1

Photographer:
WHD/DRP

Orientation:
Southeast

Description:

Cell 1 of –
Gypsum
Collection Basin



Date:
7/7/2010

Photo Number:
C2

Photographer:
WHD/DRP

PHOTOGRAPHIC LOG

Client: US EPA

Project Number: 46122

Site Name: James M. Barry Elec. Gen. Plant – Gypsum Basin

Location: Bucks, Alabama

Orientation:
Southeast

Description:

Riser Assembly
and Decant
Structure –
Gypsum
Collection Basin



Date:

7/7/2010

Photo Number:

C3

Photographer:

WHD/DRP

Orientation:

West

Description:

Gypsum
Collection Basin
– Surge pond
Pumps



Date:

7/7/2010

Photo Number:

C4

Photographer:

WHD/DRP