

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of construction activities in Interim Cap No. 2. The Woonasquatucket River is located on the left. Photograph taken facing north.

FRAME NUMBER: 6 **DATE:** 17 November 1999


TIME: 12:00 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300093



SCENE: View of ongoing construction activities in Interim Cap No. 2. Photograph taken facing northwest.

FRAME NUMBER: 11 **DATE:** 19 November 1999

TIME: 12:45 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300093

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of sampling locations CMS 700 - CMS 701, along the riverbank, located on the Brook Village property. Photograph taken facing east.

FRAME NUMBER: 14 **DATE:** 22 November 1999

TIME: 13:10 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta

SETTING: Automatic

FILM TYPE: 35-mm

FILM ROLL: BC300093



SCENE: View of concrete rubble, along the riverbank, located on the Brook Village property. Photograph taken facing east.

FRAME NUMBER: 15 **DATE:** 22 November 1999

TIME: 13:12 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta

SETTING: Automatic

FILM TYPE: 35-mm

FILM ROLL: BC300093

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of concrete rubble located on riverbank. Sample locations CMS 700 - CMS 703 are located at the lower left of the photo. Photograph taken facing east.

FRAME NUMBER: 16 **DATE:** 22 November 1999

TIME: 13:13 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300093



SCENE: View of covered riverbank area in Interim Cap No. 2. Photograph taken facing southeast.

FRAME NUMBER: 17 **DATE:** 22 November 1999

TIME: 13:15 **SKY CONDITION:** Sunny


PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300093

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of construction activities in Interim Cap No. 2. The Woonasquatucket River is located in the foreground. Photograph taken facing southeast.

FRAME NUMBER: 18 **DATE:** 22 November 1999

TIME: 13:16 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300093



SCENE: View of Interim Cap No. 2 during construction activities. Photograph taken facing south.

FRAME NUMBER: 19 **DATE:** 22 November 1999

TIME: 13:18 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300093

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of drainage channel construction in Interim Cap No. 2. Photograph taken facing north.

FRAME NUMBER: 0 **DATE:** 2 December 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 09:35 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100114




SCENE: View of installed chain-link and cedar fence sections, impeding access to the drainage swale/wetlands area. Photograph taken facing north.

FRAME NUMBER: 12 **DATE:** 8 December 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:06 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100114

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of an enhanced stormwater drainage cut adjacent to Brook Village parking lot #5. Silt fence is located in the background. Photograph taken facing west.

FRAME NUMBER: 14 **DATE:** 10 December 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:30 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100114




SCENE: View of secured riverbank area. Note enhanced stormwater drainage cut. Photograph taken facing north.

FRAME NUMBER: 15 **DATE:** 10 December 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:32 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100114

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of secured Interim Cap No. 2. Note the constructed drainage channel located in the foreground. Photograph taken facing northwest.

FRAME NUMBER: 16 **DATE:** 14 December 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta

SETTING: Automatic

TIME: 10:00

SKY CONDITION: Cloudy

WITNESS(ES): None

FILM TYPE: 35-mm

FILM ROLL: BC100144



SCENE: View of secured Interim Cap No. 2 from ground level. Photograph taken facing northeast.

FRAME NUMBER: 18 **DATE:** 14 December 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta

SETTING: Automatic

TIME: 10:10

SKY CONDITION: Cloudy

WITNESS(ES): None

FILM TYPE: 35-mm

FILM ROLL: BC100114

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed silt fence and rip-rap along the Woonasquatucket River. Note Centredale Manor located in the background. Photograph taken facing southeast.

FRAME NUMBER: 21 **DATE:** 14 December 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta

SETTING: Automatic

TIME: 10:20

SKY CONDITION: Cloudy

WITNESS(ES): None

FILM TYPE: 35-mm

FILM ROLL: BC100114



SCENE: View of the installed chain-link fence on the NEC greenway. Photograph taken facing south.

FRAME NUMBER: 25 **DATE:** 14 December 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta

SETTING: Automatic

TIME: 10:33

SKY CONDITION: Cloudy

WITNESS(ES): None

FILM TYPE: 35-mm

FILM ROLL: BC100114