

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, March 3, 2012

Kalamazoo River / Enbridge Spill

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Talmadge Creek: additional scrape near confluence.



2. Talmadge Creek: additional scrape near confluence.



3. Talmadge Creek: additional scrape near confluence.



4. Talmadge Creek: additional scrape near confluence.



5. Talmadge Creek: additional scrape near confluence.



6. Talmadge Creek: additional scrape near confluence.



7. Talmadge Creek: additional scrape near confluence.



8. Talmadge Creek restoration work near MP1.85.



9. Talmadge Creek restoration work near MP1.85.



10. Talmadge Creek restoration work near MP1.85.



11. Talmadge Creek restoration work near MP1.85.



12. Talmadge Creek excavation work near A Drive.



13. Talmadge Creek excavation work near A Drive.



14. Talmadge Creek excavation work near A Drive.



15. Talmadge Creek excavation work near A Drive.



16. Talmadge Creek: observed site prep for excavation work near A Drive.



17. Talmadge Creek near A Drive: observed pump being modified.



18. Talmadge Creek near A Drive: observed pump being modified.



19. Confluence: river levels elevated.



20. Confluence: bypass discharge.