

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, March 8, 2012

Kalamazoo River / Enbridge Spill

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Turbidity Control Structure observed being demobilized.



2. Turbidity Control Structure observed floc-box being demobilized.



3. Turbidity Control Structure observed being demobilized.



4. Turbidity Control Structure observed being demobilized.



5. Talmadge Creek: demobilizing of bypass discharge near MP1.6.



6. Talmadge Creek: the weir structure near MP1.6 has been removed.



7. Talmadge Creek: one of three small scrape locations at approximately MP1.5.



8. Talmadge Creek: one of three small scrape locations at approximately MP1.5.



9. Talmadge Creek: one of three small scrape locations at approximately MP1.5.



10. Talmadge Creek: Observed timber mat removal and restoration near MP1.8.



11. Talmadge Creek: Observed timber mat removal and restoration near MP1.8.



12. Confluence: observed the removal of the second diversion box.



13. Confluence: observed sheet piling remaining.



14. Confluence: sheet piling has been removed.



15. Confluence: observed excavation work.



16. Confluence: observed excavation around the location of the second diversion box.



17. Confluence: observed excavation around the location of the second diversion box.



18. Confluence: observed excavation around the location of the second diversion box.



19. Confluence: observed vacuum truck dewatering excavation area.



20. Confluence: observed vacuum truck off loading into frac-tanks.



21. Confluence: observed excavation around the location of the second diversion box.



22. Confluence: observed excavation around the location of the second diversion box.



23. Confluence: observed restoration of the scrape area near the red barn.



24. Confluence: observed water quality monitoring.



25. OB9.10 LDB: observed scraping operation.



26. OB9.10 LDB: observed scraping operation.



27. OB9.10 LDB: observed scraping operation.



28. OB9.10 LDB: observed back filling of scraped area.



29. OB9.10 LDB: observed sheen outside of delineated scrape area.



30. OB9.10 LDB: observed sheen outside of delineated scrape area.



31. OB9.10 LDB: observed sheen outside of delineated scrape area.



32. OB9.10 LDB: observed sheen outside of delineated scrape area.



33. OB9.10 LDB: observed sheen outside of delineated scrape area.



34. OB9.10 LDB: observed sheen outside of delineated scrape area.



35. OB9.10 LDB: observed sheen outside of delineated scrape area.



36. OB8.97 I observed standing water.



37. . OB8.97 I observed standing water.



38. OB8.97 I observed standing water.