

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/14/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/08/2012 – 0700, 03/15/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Larry Rader		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
1100	<p>Helicopter safety briefing:</p> <ul style="list-style-type: none"> • Observed timber mats staged at the farmhouse on Division Drive. • Observed crews loading up timber mats at house on 16 Mile Road. • Former Turbidity Control Structure area, observed crews removing and staging timber mats. • Observed timber mat staging area just west of 15-1/2 Mile Road. • Observed survey crews on Talmadge Creek RDB near MP 1.75. • Observed completed restoration activities on Talmadge Creek from MP 1.75 to MP 2.00. • Confluence, no sheen or turbidity issues observed. • Frac-City, observed crews decontaminating sediment control box and culvert pipe. • Former Lily Pad area, observed brown plume entering river from tributary on LDB. • Scrape activities continued at OB 9.10 LDB. • OB 9.10 LDB, observed scraping and restoration activities. • C3.2 Boat Launch, observed crews moving timber mats along shoreline. • OB 10.37 RDB, materials staged across river from planned soil scraping location. • Former MP 14.97 Island, containment boom remains in place. • South Mill Pond, water levels appear elevated. • North Mill Pond, no sheen or turbidity issues observed. • MP21.25 oxbow. No sheen or activity observed. • One boat was staged at E4 boat launch on Morrow Lake. • High altitude panoramic view of Talmadge Creek from Release Point to Confluence. No “yellow iron” observed along creek for entire 2-mile stretch. 			
1230	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				