

US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		03/16/2012	1805		
4. Unit Name/Designators		5. Unit Leader		6. Operational Period :	
Operations Unit/Overbank Branch, Recovery Group		Name:	Dan Capone & Joe Victory (START/US EPA)	From:	03/16/2012 0700
		Position:	Operations Section Chief	To:	03/16/2012 1805
7. Personnel Roster Assigned					
<u>Name</u>		<u>ICS Position</u>		<u>DUTY CELL</u>	
Dan Capone		Operations Section Chief			
Joe Victory		Operations Section Chief			
Rex Johnson		Director			
Dan Zahner		Field Team Lead			
Marc Wahrer		OBR Team #1			
8. Activity Log					
Activity Area				LAT	LAT
				Various	Various
				(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>		<u>EXTENT OF OIL IMPACTED AREA</u>			
		<u>DENSITY OF OIL /SHEEN</u>			
Total Collection Points					
Total Boom Deployed					
Activity		<p><u>Weston/START Overbank Branch Recovery Group (OBR) Team Activity:</u> OBR-1: MP 9.10 surface scrap area</p> <ul style="list-style-type: none"> Oversaw final surface scrape activities at site MP 9.10. Onsite today Craig Simon (AECOM, EI), Steve Runstrum (Enbridge OPS), Susan Jones (MDEQ) and Linda (JFNEW) onsite. Installed temporary decon area and temporary walkway at the MP 9.10 work area. Started surface scrap work in the next area for the day. The area that needed to be worked had some standing water so they had to dewater the area first and then they added sawdust and mixed the mucky soils, water and sawdust and bagged that material. This last area was in the south corner of the marked work area. This area had to be scraped to the water table as we encountered impacted soils and observed sheen and globules on the water that seeped up into the scrap area. The area was scraped to depths ranging from 16-18 inches to above water. Everyone onsite, Steve, Craig, Susan, and myself were all present and everyone agreed the bottom was still impacted but that the MDEQ did not want to go deeper than we were since we were encountering water seeping up into the area. The south back sidewall also had some impacted soils visible but no visible product. Some of the surface water and soils on the outside of the south and end did have sheen and some oily look to them, but where in the area they only wanted to try to absorb the sheen and globules. The scraped area was backfilled, seeded and coconut blanket was layed down. Coconut blanket was alos layed down on areas in the southern coner that they had used as staging 			

	<p>areas and areas they walked on a lot.</p> <ul style="list-style-type: none">• Craig also was using some absorbent pads to soak up some sheen areas we saw on the surface water in some of the areas outside the work scrap area.• AECOM collected a floor sample and Susan (MDEQ) collected a split of that sample.
Health and Safety Issues	
Comments	