

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Monday, March 19, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Demobilization of the staging area at the farmhouse on Division Drive.




2. Restoration of staging area off 16 Mile Road.



**3. Former Turbidity Control Structure area.**



**4. Timber mat staging area just west of 15-1/2 Mile Road.**



5. Frac-City decontamination activities.



6. Frac-City Soil Cells A & B.



7. Talmadge Creek near MP1.75 sheen observed.



8. Confluence, no sheen or turbidity issues observed.



9. Scrape activities resumed at OB8.97.



10. Scrape activities resumed at OB8.97.



11. Scrape area at OB9.10 restored.



12. Scrape underway at OB 10.37 RDB.



13. Scrape underway at OB 10.37 RDB.



14. MP10.37 LDB overbank sheen observed.



15. Mill Pond observed public fishing.



16. MP28.25 Oxbow observed public fishing.



17. Morrow Lake Delta.



18. Morrow Lake.