

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/20/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/15/12 – 0700, 03/22/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• OB8.97 I, soil scrape continues.</li> <li>• OB8.97 I, observed soil dewatering of scrape area.</li> <li>• OB8.97 I, observed soil tote utilized for scrape dewatering.</li> <li>• OB8.97 I, sheen observed in boomed off area.</li> <li>• OB10.37RDB, scrape work continues.</li> <li>• OB10.37RDB, observed dewatering of scrape area.</li> <li>• OB10.37RDB, observed dewatering of scrape area into tank on boat.</li> <li>• OB10.37RDB scrape area saturated.</li> <li>• Ceresco Dam, sheen observed going over spillway.</li> <li>• Confluence, no sheen or sediment observed.</li> <li>• Talmadge Creek, newly installed bridge with turbidity monitoring.</li> <li>• Talmadge Creek, crews observed installing new bridge.</li> <li>• Talmadge Creek, crews utilizing board to walk across to minimize disturbance to the creek bottom.</li> <li>• Frac-City, truck observed draining Cells A &amp; B sump.</li> <li>• Frac-City, Cell B soils remaining on site.</li> <li>• Frac-City, decontamination work.</li> <li>• Frac-City, timber mats stacked.</li> <li>• Timber mats have been demobilized from the haunted house location.</li> <li>• Observed demobilizing of staging area at the haunted house.</li> <li>• MP14.75, C5 Boat launch sheen observed.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				