

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Wednesday, March 21, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Demobilization of the staging area at the farmhouse on Division Drive appears complete.



2. Talmadge Creek/Source Area local activist observed.



3. Former Turbidity Control Structure area.



4. Frac-City decontamination activities.



5. Frac-City Soil Cells A & B.



6. Confluence, observed no turbidity or sheen.



7. Ceresco Dam.



8. Ceresco Dam observed sweep boat.



9. Ceresco Dam sheen observed flowing over spillway.



10. Ceresco Dam sheen observed flowing over spillway.



11. MP5.97 sheen and tar fleck observed downstream of Ceresco Dam.



12. MP7.0 LDB overbank RI crew observed.



13. MP 8.8 RDB overbank sheen observed in channel.



14. Scrape continuing at OB 8.97.



15. Scrape continuing at OB 8.97.



16. Scrape continuing at OB 8.97.



17. Scrape continuing at OB 8.97.



18. Scrape at OB 8.97 dewatering.



19. Scrape at OB 8.97 dewatering.



20. Scrape at OB 8.97 dewatering into tote on boat.



21. Historic Bridge Park soil staging area for the OB8.97.



22. Scrape work at OB10.37 continues.



23. Scrape activities continued at OB10.37 RDB.



24. Scrape work at OB10.37 RDB continues.



25. MP14.75 C5 Boat Launch.



26. MP14.75 C5 Boat Launch sheen observed.



27. MP14.75 C5 Boat Launch observed crew taking water and sediment temperatures.



28. MP27.5 observed sampling crews.



29. Morrow Lake Delta.



30. Morrow Lake.