

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, March 22, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Confluence poling along the boom and curtain.



2. Confluence poling along the boom and curtain.



3. Ceresco Dam SWAT crew observed deploying boom.



4. Ceresco Dam SWAT crew observed deploying boom.



5. Ceresco Dam SWAT crew observed deploying boom.



6. Ceresco Dam SWAT crew observed deploying boom.



7. Ceresco Dam sheen collecting within boom.



8. Ceresco Dam sheen collecting within boom.



9. OB10.37RDB backfill being utilized.



10. OB10.37RDB backfill being utilized.



11. OB10.37 RDB scrape work continued.



12. OB10.37 RDB scrape work continued.



13. OB10.37 RDB restoration of scrape area.



14. OB8.97 I scrape work continued.



15. OB8.97 I scrape work continued.



16. Island A tar globs and sheen observed.



17. Island A tar globs and sheen observed.



18. Island A tar globs and sheen observed.



19. Sheen observed RDB above Ceresco Dam.



20. Sheen observed RDB above Ceresco Dam.