

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, March 27, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. MP30.0 sheen observed at E4 boat launch. Sheen observed after boat was launched.




2. MP30.0 sheen observed at E4 boat launch. Sheen observed after boat was launched.



3. MP32.0 LDB during river assessment observed absorbent boom from last year submerged oil work was observed. SWAT disposed of boom.



4. MP32.0 sheen observed in center of river channel. Typical size of sheen spots observed in river system when observed.



5. MP33.0 LDB former submerged oil location sheen observed.



6. MP33.0 LDB former submerged oil location sheen observed.