

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Wednesday, March 28, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Demobilization of the staging area at the farmhouse on Division Drive appears complete.



2. Frac-City observed foot print reduction.



3. Frac-City no decontamination activities observed.



4. Frac-City Soil Cells A & B.



5. Timber mat staged off Talmadge Creek near MP1.5.



6. Confluence, observed no turbidity or sheen.



7. Survey crew observed at Saylor Landing.



8. MP2.5 LDB sheen observed.



9. MP2.75 RDB sheen observed.



10. Ceresco Dam observed newly installed boom.



11. OB 8.48 LDB.



12. MP8.48 LDB.



13. OB8.97 crew observed.



14. MP10.5 SORT crew observed.



15. MP15.75 boom installed at the Battle Creek Spillway.



16. Morrow Lake Delta.



17. Morrow Lake E4 Boom installed.



18. Morrow Lake.