

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, March 30, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. OB10.37 hexane test.



2. MP17.0 LDB RockTenn sheen observed within boom.



3. MP17.0 LDB RockTenn sheen observed within boom.



4. Talmadge Creek entering into the confluence no sheen or turbidity observed.



5. Confluence no turbidity or sheen observed.



6. Talmadge Creek south of A Drive no turbidity or sheen observed.



7. Frac-City timber mats observed being shredded.



8. Frac-City timber mats observed being shredded.