

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, March 31, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:


Matthew Haak
START-USEPA
Situation Unit Leader



1. MP9.00 R1 sheen observed.



2. Hexane Test at MP9.00 R1.



3. MP9.00 R1 hexane test result.



4. MP9.00 R1 hexane test result.



5. MP11.25R2 sheen observed.



6. MP11.25R2 hexane test result.



7. MP11.25R2 sheen observed.



8. MP11.25R2 hexane test result.



9. MP11.25R2 sheen observed.



10. MP11.25R2 hexane test result.



11. MP11.75 LDB sheen observed.



12. MP11.75 LDB hexane test result.



13. Ceresco Dam boom.



14. Ceresco Dam sheen observed.