

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, April 10, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Confluence, sediment control structure.



2. SWAT crews observed deploying buoys at the Confluence.



3. SWAT crews observed deploying buoys at the Confluence.



4. SWAT crews observed deploying buoys at the Confluence.



5. SWAT crews observed deploying buoys at the Confluence.



6. SWAT crews observed deploying buoys at the Confluence.



7. SWAT crews observed deploying buoys across from the Confluence at a side channel.



8. Buoys deployed across from the Confluence at a side channel.



9. Buoys deployed at the confluence.



10. SWAT crew deploying buoy east of 15 Mile RD just up from Saylor's Landing.



11. SWAT crew deploying buoy at Saylor's Landing.



12. SWAT crew deploying buoy at Saylor's Landing.



13. Observed crew deploying Walling Tubes upstream of the confluence.



14. Observed crew deploying Walling Tubes upstream of the confluence.



15. Observed crew adjusting Walling Tube within the water column.



16. Observed crew deploying second Walling Tube at this location upstream of the confluence.



17. New boom configuration above Ceresco Dam.



18. New boom configuration above Ceresco Dam.



19. New boom configuration above Ceresco Dam.



20. Observed crew reducing the foot print at the C0.4 boat launch.



21. Observed crew reducing the foot print at the C0.4 boat launch.



22. Observed crew reducing the foot print at the C0.4 boat launch.