

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Wednesday, April 18, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Segment 1 open.




2. Cleaning station at Perrin Dam launch site.



3. Kiosk material placed at Perrin Dam launch site.



4. Kiosk material placed at Perrin Dam launch site.



5. Kayak trip down open Segment 1.



6. Kayak trip down open Segment 1.



7. Buoys removed from the confluence.



8. Saylor's Landing .



9. Ceresco Dam boom.



10. Sheen observed at Ceresco Dam.