

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, April 23, 2012

Kalamazoo River / Enbridge Spill

Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Launch point for open river section. River level has dropped since Friday.



2. Frac Tank City, crews continue to reduce footprint in northern end of area.



3. Frac Tank City soil cells A and B, no materials staged in cells.



4. Frac Tank City decon area. No activity observed.




5. Walling tube at Confluence. Creek water level has dropped since Friday.




6. Confluence. No turbidity or sheen observed. Creek and river levels have dropped since Friday.



7. Ceresco Dam. Crews staging equipment and beginning utility location for construction of access point below dam.



8. Ceresco Dam. Crews beginning activities associated with construction of public access point.



9. Boat crews removing debris from containment boom above Ceresco Dam.



10. Chevron Boom at Battle Creek spillway. No sheen or debris observed.



11. Morrow Lake. Poling crews shut down boat operations due to high winds on lake.



12. Control point at E4 boat launch. No sheen or debris observed.