

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, April 27, 2012


Kalamazoo River / Enbridge Spill

Weather / River Conditions from Thursday (4-26-2012)

Conditions: Cloudy

Average River Water Temperature: 50° F

Average River Sediment Temperature: 51 ° F



Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Crews building sediment collection devices for installation with sediment traps.



2. Close up of sediment collection device interior.



3. Crews continue footprint reduction at Frac Tank City.



4. Gravel removal in northern end of Frac Tank City.




5. Southern decon pad at Frac Tank City. Boom and materials staged in pad.



6. Crews conducting boom inspection and maintenance above Ceresco Dam.



7. Pond at former OB 5.92 RDB excavation location. Area inspected by Operations today.



8. Operations crews inspecting shoreline at MP5.92 LDB.



9. Former excavation site at MP 9.10. Area inspected by Operations today.



10. Former excavation location at MP 8.97. Area inspected by Operations crews today.



11. Operations crew inspecting former 10.37 excavation area.



12. Operations personnel inspecting former excavation area at MP 11.25.



13. Restoration at former excavation area at MP 11.25 R2. Operations personnel inspected this location today.



14. Operations personnel inspecting former excavation location at OB 13.40 RDB.



15. Sediment trap materials staged at former D2 boat launch, across the river from MP 19.25 LDB sediment trap location.



16. Crews off-loading materials for sediment trap installation at MP 19.25 LDB.



17. Crews continue poling activities in northeastern portion of Morrow Lake.



18. Control Point E4, no sheen observed.