

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, May 19, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Friday (5-18-2012)

Conditions: Sunny

Ambient Air Temperature High: 79° F

Average River Water Temperature: 67° F

Average River Sediment Temperature: 65° F



Prepared by:
Larry Rader
START-USEPA
Situation Unit Leader



1. Poling crews working upstream of Ceresco Dam.



2. Sheen observed above Ceresco Dam within containment.



3. Control Point at Ceresco Dam, sheen and debris observed in containment.



4. Sheen ribbons observed within containment above Ceresco Dam.



5. Poling crews near MP 6.75.



6. Poling crews near MP 6.75.



7. MP 8.48 containment boom.



8. Sheen observed within containment at MP 8.48 LDB.



9. Sediment trap at MP 10.75 LDB. Sheen observed within containment.



10. Sheen observed within containment at MP 10.75.




11. Poling crews using ARGO all-terrain vehicles in backchannel near MP 11.25 LDB.



12. Poling crews using ARGO all-terrain vehicles in backchannel near MP 11.25 LDB.



13. Sheen along backchannel shoreline at MP 11.25 LDB.



14. Sheen along backchannel shoreline at MP 11.25 LDB. Support boat present to collect sheen.



15. MP 14.98 Island. Containment boom remains in place around island.



16. Culverts at MP 15.75, north end of Mill Ponds, no sheen observed.



17. Control Point E4, crews observed removing debris within containment.



18. Sheen and debris within containment at Control Point E4.



19. Poling crews in southwestern portion of Morrow Lake.



20. Poling crews in west central portion of Morrow Lake.



21. Poling crew in southwestern portion of Morrow Lake.



22. Poling crews on Morrow Lake mobilizing to next poling location.



23. Poling crew observed downstream of Morrow Lake Dam.



24. Poling crew below spillway of Morrow Lake Dam.