

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, May 29, 2012

Kalamazoo River / Enbridge Spill

Weather / River Conditions for Tuesday (5-29-2012)

Conditions: Sunny

Ambient Air Temperature High: 80° F

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Source area pond, no sheen observed.



2. Frac-Tank City decon pad and soil cells. Boat observed in decon area.



3. Frac-Tank City, footprint reduction continues.



4. Confluence, no turbidity or sheen observed.



5. Observed public utilizing Saylor's Landing.



6. MP4.5 LDB, no sheen observed.



7. Above Ceresco Dam, sheen observed.




8. Control point above Ceresco Dam, some debris observed within containment.



9. MP10.75 sheen observed within boom.



10. MP13.0 land owner mowed field.



11. MP15.75 Mill Ponds culverts, sheen observed within containment.



12. MP21.5, no sheen observed within boom.



13. MP26.0 RDB sheen observed.



14. MP26.25 RDB sheen observed.



15. MP 28.25 oxbow, sheen observed within oxbow.



16. MP30.8 LDB no sheen observed.



17. Morrow Lake Delta sheen observed around sandbar.



18. Morrow Lake Delta sheen observed around sandbar.



19. Control Point E4 no sheen observed.



20. No activity observed below Morrow Lake Dam.