

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, May 30, 2012

Kalamazoo River / Enbridge Spill


## Weather / River Conditions for Wednesday (5-30-2012)

Conditions: Partly Sunny

Ambient Air Temperature High: 69° F

Average River Water Temperature: 70.65° F

Average River Sediment Temperature: 69.27° F



Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Ceresco Dam containment boom.



2. Sheen observed between booms at Ceresco Dam.





3. Sheen observed outside of boom at Ceresco Dam.



4. Sheen observed outside of boom at Ceresco Dam.



5. Sheen observed outside of boom at Ceresco Dam.



6. Legacy work below Ceresco Dam.






7. OB5.92 RDB sheen observed in pond.



8. OB5.92 RDB sheen observed in pond.



9. MP15.75 crew observed cleaning out control point.



10. MP15.75 sheen and debris observed near culvert.





11. MP15.75 sheen observed flowing through culvert.



12. MP15.5 Mill Ponds poling crew observed.





13. MP15.5 Mill Ponds poling crew observed.



14. MP21.5 sheen observed within the river channel outside of containment.





15. MP21.5 sheen observed within the river channel outside of containment.



16. MP26.75 poling crew observed.





17. MP26.25 RDB sheen observed.



18. MP26.25 RDB sheen observed.



19. MP26.25 RDB sheen observed.



20. MP26.0 RDB sheen observed.





21. MP26.0 RDB sheen observed.



22. MP26.0 sheen observed.



23. Sweep boat mobilizing to MP26.0 and MP26.25.



24. MP28.25 sheen observed after jet boat reverse thrust.





25. MP28.25 sheen observed after jet boat reverse thrust.



26. MP28.25 sheen observed after jet boat reverse thrust.





27. MP28.25 sheen observed after jet boat reverse thrust.



28. MP30.8 containment boom sheen observed within boom.





**29. MP30.8 sheen observed within boom.**



**30. Morrow Lake Delta poling crews.**



31. Morrow Lake Delta poling crews.



32. Morrow Lake Delta poling crews.





**33. Morrow Lake Delta sheen observed.**



**34. Morrow Lake Delta sheen observed.**



**35. Morrow Lake Delta sheen observed.**



**36. Morrow Lake poling crew.**





37. Morrow Lake sheen sweep boat.



38. Sheen observed around boat after docking at Shady Bend Campground.