

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/31/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/31/12 – 0700, 06/07/12
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Leader	Houston, Texas	
8. Activity Log			
Time	Major Events		
09:00	Operational status: - MP7.89 LDB, woody debris removal crew. - MP7.89 LDB, sheen observed when the boat docked along the shoreline. - MP8.48, Sheen observed within boom. - MP8.75 RDB, boom no sheen observed. - MP9.75, RDB, poling crew observed. - MP9.75 RDB, poling crew observed. - MP10.75, sediment control trap, water levels recieding. - MP10.75, sheen observed within the boom. - MP10.75, poling crew observed. - MP10.0 C3.2 boat launch, sheen observed around docking boats. - Ceresco Dam, sheen and debris collecting at boom. - Ceresco Dam, sheen observed between two booms. - Ceresco Dam, sheen observed down stream of boom. - Ceresco Dam, tar glob bound to vegetation flowing over dam. - Ceresco Dam, sheen observed flow over dam. - C0.4 Boat launch, sheen observed bound in vegetation. - MP37.75, Poling crew observed just below E4 boom. - Morrow Lake Dam, velocity study observed. - MP38.75 north shore, Morrow Lake sheen observed. - Morrow Lake, sweep boat responding to sheen observed. - MP38.25, Morrow Lake sheen observed. - MP38.00, Morrow Lake north cove sheen observed.		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			