

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, May 31, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Thursday (5-31-2012)

Conditions: Partly Cloudy/Rain


Ambient Air Temperature High: 55° F

Average River Water Temperature: 64.81° F


Average River Sediment Temperature: 65.13° F



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. MP7.89 LDB woody debris removal crew.



2. MP7.89 LDB sheen observed when the boat docked along the shoreline.



3. MP8.48 LDB boom.



4. MP8.48 Sheen observed within boom.



5. MP8.48 LDB boom no sheen observed.



6. MP8.75 RDB boom no sheen observed.



7. MP9.75 RDB poling crew observed.



8. MP9.75 RDB poling crew observed.



9. MP9.75 RDB poling crew observed.



10. MP10.75 sediment control trap, water levels receding.



11. MP10.75 sheen observed within the boom.



12. MP10.75 poling crew observed.



13. MP10.0 C3.2 boat launch sheen observed around docking boats.



14. Ceresco Dam sheen and debris collecting at boom.



15. Ceresco Dam sheen observed.



16. Ceresco Dam sheen observed.



17. Ceresco Dam sheen observed between two booms.



18. Ceresco Dam sheen observed down stream of boom.



19. Ceresco Dam tar glob bound to vegetation flowing over dam.



20. Ceresco Dam sheen observed flow over dam.



21. Ceresco Dam, owner is having turbines removed.



22. C0.4 Boat launch sheen observed.



23. C0.4 Boat launch sheen observed.



24. C0.4 Boat launch sheen observed.



25. C0.4 Boat launch sheen observed.



26. C0.4 Boat launch sheen observed bound in vegetation.



27. MP37.75 Poling crew observed just below E4 boom.



28. MP37.75 Poling crew observed just below E4 boom.



29. Morrow Lake poling crew.



30. Morrow Lake Dam velocity study observed.



31. Morrow Lake Dam velocity study observed.



32. Morrow Lake Dam velocity study observed.



33. MP38.75 north shore Morrow Lake sheen observed.



34. MP38.75 north shore Morrow Lake sheen observed.



35. Morrow Lake sweep boat responding to sheen observed.



36. MP38.25 Morrow Lake sheen observed.



37. MP38.25 Morrow Lake sheen observed.



38. MP38.25 Morrow Lake sheen observed.



39. MP38.00 Morrow Lake north cove sheen observed.



40. MP38.00 Morrow Lake north cove sheen observed.