

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, June 19, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Monday (6-18-2012)

Conditions: Late Morning Rain / Sunny Afternoon

Ambient Air Temperature High: 93° F

Average River Water Temperature: 72.79° F

Average River Sediment Temperature: 68.71° F



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Source area pond.



2. Frac-City observed boom being decontaminated.



3. Frac-City observed boom being decontaminated.



4. Confluence, no sediment or sheen observed.



5. MP5.0 Sweep boat observed.



6. Ceresco Dam boom has been removed.



7. MP5.63 Observed crew removing vegetation.



8. Ceresco Dam sheen observed.



9. Ceresco Dam sheen observed.



10. Ceresco Dam containment branch crew observed.



11. Ceresco Dam portage work continued.



12. Ceresco Dam sheen observed.




13. MP8.4 Boom removed.



14. MP8.45 Boom removed.



15. MP8.75 Reassessment crew observed.



16. MP8.9I Reassessment crew observed.



17. MP10.75 Sediment trap.



18. MP11.75 Boom removed.



19. MP13.0 Sheen observed in river channel.



20. MP13.75 Reassessment crew observed in overbank area.



21. MP15.75 Boom observed being removed.



22. MP15.75 Boom observed being removed.



23. MP17.5 Poling crew observed.




24. MP27.75 sheen sweep boat observed.



25. MP28.25 Poling crew observed.



26. MP28.25 Oxbow sheen observed.



27. MP29.0 Reassessment crews observed.



28. MP33.0 Reassessment crew observed.



29. MP36.5 Reassessment team observed.



30. Morrow Lake Delta buoys deployed.



31. Morrow Lake Delta buoys deployed.



32. Morrow Lake Delta buoys deployed.




33. Morrow Lake Delta sheen sweep observed at E4 boom.



34. Morrow Lake Delta sheen observed.



35. Morrow Lake poling crew.



36. Morrow Lake poling crew.



37. Morrow Lake velocity boat and sheen sweep boat observed.



38. Morrow Lake Dam.