

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, June 23, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Friday (6-22-2012)

Conditions: Sunny

Ambient Air Temperature High: 85° F

Average River Water Temperature: 76.22° F

Average River Sediment Temperature: 71.46° F



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Sheen observed at Ceresco Dam.



2. Sheen observed at Ceresco Dam.



3. Ceresco Dam temporary portage.



4. Ceresco Dam Portage under construction.



5. Ceresco Dam sweep boat.



6. Ceresco Dam temporary portage.



7. Ceresco Dam sheen observed portage.



8. Ceresco Dam downstream put in.



9. Boom removed from below Ceresco Dam.



10. Sheen observed at E4 boat launch.



11. Sheen observed at E4 boat launch.



12. Morrow Lake observed public utilizing the lake.



13. Morrow Lake Delta observed crew installing boom anchors.



14. Morrow Lake Delta observed crew installing boom anchors.



15. Morrow Lake Delta observed installed boom anchors.



16. E4 Boat Launch crew loading boom to be deployed.



17. Morrow Lake Fan sheen observed.



18. Morrow Lake Fan sheen observed.