

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Saturday, June 30, 2012

Kalamazoo River / Enbridge Spill


## Weather / River Conditions for Friday (6-29-2012)

Conditions: Overcast

Ambient Air Temperature High: 87° F

Average River Water Temperature: 79.69° F

Average River Sediment Temperature: 76.41° F



Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Ceresco Dam portage work continued below the dam.



2. Ceresco Dam observed sheen sweep boat.



3. Ceresco Dam sheen observed along the south side of the dam at the dam.



4. Ceresco Dam observed sheen sweep boat.



5. Ceresco Dam sheen observed along the south side of the dam at the dam. Sweep boat restricted from accessing this area.



6. Observed sheen sweep boat operating around the railroad trestle.



7. Observed sheen around the railroad trestle. Sheen sweep boat operating in the area.



8. MP14.75 Sediment trap.



9. MP14.75 Sheen observed when boat reversed.



10. C5 Boat launch, observed sheen sweep boat deploying.



11. MP15.5 North end of south Mill Pond observed sheen flowing out into the river.



12. MP15.5 Observed sheen sweep boat operating in the area of sheen sighting.



13. Morrow Lake observed sweep boat operating in the southeast corner.



14. Morrow Lake observed additional sweep boat operating in the northeast cove.



15. Morrow Lake sheen observed in the southeast cove. Sweep boat was operating in the area.



16. Morrow Lake Delta E4 boom system buoys deployed along the boom.



17. Morrow Lake Delta E4 boom system, new boom installed along the northern shore.



18. Morrow Lake Delta E4 boom system, new boom installed along the northern shore.



19. Morrow Lake Delta E4 boom system, new boom installed along the northern shore.



20. Morrow Lake sheen observed along the northern shoreline near newly installed boom. Sheen sweep boat operating in the Delta.



**21. Morrow Lake Delta observed sheen sweep boat operating along the southern shoreline.**



**22. Morrow Lake Delta observed crew installing E4 boom system anchor in the southeast corner of Delta.**



**23. Morrow Lake Delta observed crew installing E4 boom system anchor in the southeast corner of Delta.**



**24. Morrow Lake Delta observed crew installing E4 boom system anchor in the southeast corner of Delta.**



**25. Morrow Lake Delta observed sheen in the southeast corner of Delta.  
Sheen sweep boat was operating in the Delta.**



**26. Morrow Lake Delta E4 boom system. Buoys being deployed around the boom.**