

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, July 2, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Monday (7-2-2012)

Conditions: Sunny

Ambient Air Temperature High: 93° F

Average River Water Temperature: 77.97° F

Average River Sediment Temperature: 70.95° F



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Source area pond no sheen observed, pond water levels quickly receding.



2. Frac-City observed boom staged at the decontamination pad.



3. Former Talmadge Creek dewatering pad location. Observed soil grading occurring.



4. Confluence seen observed.



5. MP2.75 LDB sheen observed.



6. MP2.75 LDB sheen observed.



7. MP5.25 observed sheen sweep boat operating. Observed sheen within disturbed sediment.



8. MP5.63 LDB sheen observed. Sweep boat was observed operating in the area.



9. Ceresco Dam sheen sweep boat observed.



10. Ceresco Dam sheen observed along the RDB just upstream from the dam.



11. Ceresco Dam sheen observed along the RDB just above the dam.



12. Ceresco Dam portage work observed below the dam.



13. MP6.5 Island sheen observed.



14. MP7.25 RDB observed RI crew.



15. MP9.5 Historic Bridge Park observed sweep boat.



16. Paddler's Grove observed handicap boat launch being installed.



17. MP15.75 RDB North Mill Pond observed sheen.



18. MP17.0 RDB sheen observed.



19. MP17.25 RDB sheen observed.



20. MP17.5 LDB sheen observed.



21. MP17.5 LDB sheen observed.



22. MP21.5 LDB sheen observed.



23. MP22.0 observed sheen sweep boat moving up stream.



24. MP26.25 LDB sheen observed.



25. Morrow Lake Delta observed crews installing anchors for the E4 Boom System.



26. Morrow Lake Delta observed crews installing anchors for the E4 Boom System.



27. Morrow Lake Delta observed anchors for the E4 Boom System.



28. Morrow Lake Delta observed anchors for the E4 Boom System.



29. Morrow Lake Delta boats agitated sediment and sheen observed.



30. Morrow Lake Delta boom installed as part of the E4 Boom System.



31. Morrow Lake Delta E4 Boom System.



32. Morrow Lake Delta E4 Boom System.



33. Morrow Lake observed sweep boat operating in the north cove.



34. Morrow Lake poling crew observed in the southwest corner of the lake.



35. Morrow Lake southeast cove sheen observed.



36. Morrow Lake film observed.