

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, July 5, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Thursday (7-5-2012)

Conditions: Sunny

Ambient Air Temperature High: 100° F

Average River Water Temperature: 87° F

Average River Sediment Temperature: 79° F



Prepared by:
Larry Rader
START-USEPA
Situation Unit Leader



1. Source area pond, sheen observed.



2. Frac-City, observed crews cleaning boom in the decon pad.



3. Former Talmadge Creek dewatering pad location. Observed crew loading mats onto a truck at this location.



4. Confluence, no sheen observed.



5. Lily Pad area, no sheen observed.



6. South peninsula above Ceresco Dam, observed sheen on downstream side of peninsula. Sheen sweep boat was notified.



7. Sheen observed above Ceresco Dam. Sweep boat was observed operating in the area.




8. Ceresco Dam, sheen observed in southwest corner above dam and in river channel. Sheen sweep boat was notified.




9. Ceresco Dam, sheen and globules observed along the RDB, just upstream from the dam.



10. Ceresco Dam, sheen observed along the LDB along the southern wall of the dam.



11. MP6.5, group of kayakers observed.



12. Sheen sweep boat observed near MP 14.0.



13. South side of Mill Pond, no sheen observed. One sweeper boat observed near bridge.



14. MP 19.25 sediment trap, no sheen observed.



15. Sheen sweep boat operating near MP27.5.



16. Morrow Lake Delta, current configuration of E4 Boom System.



17. Crews inspecting the curtain along the E4 Boom System.



18. Morrow Lake Delta, Crews installing boom in southern of delta. Sheen observed in vicinity of boat.



19. Morrow Lake Delta, sheen observed along southern shore in vicinity of boats.



20. Morrow Lake, sheen sweep pontoon operating in northern portion of lake.



21. Fishing boat observed in northwestern corner of Morrow Lake.



22. Morrow Lake Dam, no sheen observed.