

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/10/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
13:00	<p>Helicopter Safety Briefing, take off.</p> <p>Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond, sheen observed.</li> <li>• Frac-City, no activity observed.</li> <li>• Confluence, no sheen observed.</li> <li>• River velocity measurement crew observed measuring transect near MP5.4.</li> <li>• Sheen observed along LDB just downstream from C0.4 boat launch, sweeper boat notified.</li> <li>• South peninsula above Ceresco Dam, observed sheen on downstream side of peninsula. Sheen response crews were notified.</li> <li>• Vegetation and turbidity observed in vicinity of Ceresco Dam control point.</li> <li>• RI crew observed along LDB near MP 8.0.</li> <li>• Observed upstream side of MP 10.75 sediment trap. Inlet is almost dry.</li> <li>• Boat crew observed along LDB near MP 12.0.</li> <li>• South end of Mill Pond, two sweeper boats observed. No sheen observed.</li> <li>• North end of Mill Pond and Battle Creek spillway, no sheen observed.</li> <li>• Boat crew observed moving downstream near MP 18.00.</li> <li>• Downstream side of MP19.25 sediment trap, no sheen observed.</li> <li>• Oxbow at MP21.5, no sheen observed.</li> <li>• Sheen sweeper boat observed near MP 25.00.</li> <li>• East end of Morrow Lake Delta, no sheen or activity observed.</li> <li>• E 3.5 containment boom installed in southern end of Morrow Lake Delta.</li> <li>• Current boom configuration at E4 control point.</li> <li>• Poling crew observed in central portion of Morrow Lake.</li> <li>• Canoe fisherman observed in central portion of Morrow Lake.</li> <li>• South shore of Morrow Lake south of the fan. No sheen observed here today.</li> <li>• Morrow Lake Dam, no sheen or activity observed.</li> </ul>			
	Additional observations: None			
15:30	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				