

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, July 13, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions:

Conditions: Sunny

Ambient Air Temperature High: 92° F

Average River Water Temperature: 78° F

Average River Sediment Temperature: 76° F



Prepared by:
Larry Rader
START-USEPA
Situation Unit Leader



1. Plant staging area set up along Division Drive for Talmadge Creek tree planting activities.



2. Trees unloaded and stored in shade for planting along Talmadge Creek.



3. Crew transporting debris bags from Ceresco Dam control point upstream to C0.4 boat launch.



4. Sheen and vegetation observed at former trestle above Ceresco Dam.



5. Vegetation and sheen observed along containment boom above Ceresco Dam.



6. Globules and sheen within containment above Ceresco Dam.



7. Recreational boaters near MP 15.0 upstream from the Mill Ponds.



8. Sheen sweep boat operating in the southern half of the Mill Pond.



9. View of MP 21.5 oxbow from Custer Road Bridge. Sheen sweep boat observed operating downstream from bridge.



10. Sheen sweep boat observed downstream from MP 21.5 oxbow.



11. Sheen sweep boat operating in Morrow Lake Delta.



12. Morrow Lake Delta poling crew moving to next poling location.



13. Sediment curtain inspection crew working at E 4.0 control point.



14. Recreational air boat observed along southern of Morrow Lake.