

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, July 17, 2012

Kalamazoo River / Enbridge Spill

Weather / River Conditions for Today


Conditions: Sunny

Ambient Air Temperature High: 98° F

Average River Water Temperature: 83.46° F

Average River Sediment Temperature: 79.30° F

Water and Sediment Temperature



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Source area pond nearly dry.




2. Talmadge Creek restoration work.



3. Talmadge Creek restoration work.



4. Frac-Tank City observed boom being decontaminated.



5. Frac-Tank City observed boom being decontaminated.



6. Ceresco Dam boom maintenance/sweep boat observed at C0.4 boat launch.



7. Railroad trestle above Ceresco Dam, observed sheen on downstream side. Operations was notified.



8. Ceresco Dam portage work.



9. Ceresco Dam observed debris removal from the control point.



10. Ceresco Dam sheen observed. Sheen was generated from the boom maintenance boat.



11. Ceresco Dam decibel monitoring station.



12. Flight back up river, observed sheen sweep boat at MP5.25 LDB.



13. MP5.25 Sheen observed along LDB behind the sheen sweep boat.



14. MP8.25 RI crew observed.



15. MP9.75 RDB sheen observed.



16. MP9.75 LDB sheen observed.



17. MP15.5 South Mill Pond, no sheen observed.



18. Sheen sweeper boat observed at MP 21.5.



19. MP28.25 decibel monitoring station.



20. Morrow Lake Delta poling crew just west of 35th Street Bridge.



21. Morrow Lake Delta poling crew observed.



22. Morrow Lake Delta, observed boom maintenance along Boom B.



23. Morrow Lake Delta sheen observed along Boom A.



24. Morrow Lake observed sweep boat operating south of Rowe Island.