

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, July 31, 2012

Weather / River Conditions for Tuesday July 31, 2012


Conditions: Sunny

Ambient Air Temperature High: 85° F

Average River Water Temperature: 76.05° F

Average River Sediment Temperature: 74.95° F

Water and Sediment Temperature



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Ceresco Dam Control Point Boom, debris observed prior to boom maintenance crew arriving.



2. Ceresco Dam sheen observed collecting in the control point.



3. Ceresco Dam portage decontamination station observed.



4. Morrow Lake poling team observed.



5. Morrow Lake Delta Boom F, observed a sweep boat operating.



6. Morrow Lake Delta Boom C, observed sheen collecting along the boom.



7. Morrow Lake Delta Boom C, observed boom maintenance crew.



8. MP36.25 RDB sheen was observed, no sweep boat was warranted.



9. MP36.25 RDB sheen was observed, no sweep boat was warranted.



10. Morrow Lake observed the sweep boat operating.



11. MP27.0 RDB observed river bank erosion restoration work.



12. MP26.0 RDB, observed ribbons of sheen, sheen sweep boat not warranted.



13. MP5.25 RDB sheen observed.



14. MP23.10 RDB sheen observed, no sweep boat was warranted.



15. MP23.10 RDB sheen observed, no sweep boat was warranted.



16. MP22.6 observed newly fallen tree branch obstructing river navigation.



17. MP21.5 Custer Bridge sheen observed, no sweep boat warranted.



18. MP21.5 Custer Bridge sheen observed, no sweep boat warranted.



19. MP5.45 LDB observed sheen, sheen sweep boat was observed operating in the area.



20. MP5.45 LDB observed sheen, sheen sweep boat was observed operating in the area.



21. MP5.63 LDB Railroad trestles sheen observed, sheen sweep boat was observed operating in the area.



22. MP5.63 LDB Railroad trestles sheen observed, sheen sweep boat was observed operating in the area.



23. Ceresco Dam control point boom, observed the debris removed from the boom.



24. Ceresco Dam control point boom, observed sheen and tar glob collecting at the boom.



25. Observed the sheen sweep boat operating above Ceresco Dam.



26. Source area observed crew pulling well casing.



27. Source area coring work.



28. Source area coring work.