

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Thursday, August 3, 2012

Kalamazoo River / Enbridge Spill

## Weather / River Conditions for Friday, August 3, 2012


Conditions: Sunny

Ambient Air Temperature High: 91° F

Average River Water Temperature: 75.42° F

Average River Sediment Temperature: 75.93° F

### Water and Sediment Temperature



Prepared by:  
Dan Zahner  
START-USEPA  
Situation Unit Leader

Data as of 08/02/2012, 08/03/2012 data unavailable



1. MP 5.0 RDB.



2. MP 5.0 RDB sheen observed.



3. MP 5.0 to MP 5.63 LDB sheen observed, sheen sweep boat observed working in the area.



4. MP 5.25 sheen observed, sheen sweep boat observed working in the area.



5. MP 5.55 observed sheen sweep boat operating.



6. Ceresco Dam control point boom, observed vegetative debris and sheen.



7. Ceresco Dam control point boom, observed vegetative debris and sheen.



8. MP 10.50 L2 Sediment Trap.



9. MP 12.15 east side of Raymond Road culvert, site for coir log structure installation at MP 11.79 Sediment Trap.



MP 15.25, South Mill Pond.



10. MP 26.00 RDB sediment trap location, no sheen observed.



11. MP 26.75 RDB river bank restoration location.



12. MP 30.8 LDB sediment trap location, no sheen observed.



13. MP 30.8 LDB sediment trap.



14. Morrow Lake Delta, no sheen observed.



15. Morrow Lake Delta Gate E North, vegetative debris collecting.



16. Morrow Lake observed the sweep boat operating.