

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, August 15, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Source Area sheen observed.



2. Source Area sheen observed.



3. Frac-City decontamination pad, no activity observed.



4. Frac-City observed crews consolidating materials.



5. MP5.63 observed the sheen sweep boat operating.



6. MP5.63 LDB sheen observed.



7. MP5.9 RDB sheen observed.



8. MP7.0 "Nook" sheen observed.



9. MP10.75 absorbent boom remains in place, no sheen observed.



10. MP15.25 Burnham Street Bridge observed sheen flowing within the river channel.



11. MP15.25 Burnham Street Bridge observed sheen flowing within the river channel.



12. MP15.25 Burnham Street Bridge observed sheen flowing within the river channel.



13. MP19.25 Observed crews performing monthly sediment trap monitoring.



14. MP19.25 Observed crews performing monthly sediment trap monitoring.



15. MP21.5 Custer Drive Bridge, observed Situation crew.



16. MP21.5 Custer Drive Bridge sheen observed. No sweep boat warranted.



17. MP 26.00 RDB sheen observed.



18. MP 26.00 RDB sheen observed.



19. MP 26.25 RDB sheen observed.



20. MP27.0 RDB observed shoreline restoration work.



21. MP36.25 area where sheen was observed.



22. MP36.25 sheen was observed. Sweep boat was not warranted.



23. Morrow Lake Delta, observed crew inspecting Delta A.



24. Morrow Lake Delta Boom B, observed sheen collecting along the boom.



25. Morrow Lake Delta Boom B, observed sheen when boat reversed.



26. Morrow Lake Delta Boom C, observed sheen and debris collecting along the boom.



**27. Morrow Lake Delta Boom C, observed crew removing sheen and debris collecting along the boom.**



**28. Morrow Lake Delta Boom E, observed crew removing sheen and debris collecting along the boom.**




29. Morrow Lake observed crew redeploying Walling Tube sampling devices.



30. Morrow Lake observed crew redeploying Walling Tube sampling devices.



31. Morrow Lake area where sheen was observed.



32. Morrow Lake sheen was observed between Rowe Island and the small island.



**33. Morrow Lake sheen was observed between Rowe Island and the small island.**



**34. Morrow Lake sheen was observed between Rowe Island and the small island.**



35. Morrow Lake southwest cove sheen observed.



36. Morrow Lake Dam.