


US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, August 21, 2012

Kalamazoo River / Enbridge Spill

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Ceresco Dam kiosk with no documentation observed and no decontamination station observed.



2. Ceresco Dam control point boom.



3. MP5.3 LDB sheen and tar globs observed.



4. MP5.5 LDB sheen and tar globs observed.



5. MP5.5 LDB sheen and tar globs observed.



6. MP5.55 center channel sheen and tar globs observed.



7. MP5.63 LDB sheen and tar globs observed.



8. MP5.63 LDB sheen and tar globs observed.




9. MP5.63 LDB sheen and tar globs observed.



10. Ceresco Dam control point boom observed sheen collecting along the boom.



11. Ceresco Dam observed a crew performing debris removal from the boom.



12. MP5.55 RDB sheen observed.




13. MP5.0 RDB tar globs and sheen observed.



14. MP4.5 no sheen observed.



15. MP10.75 no sheen observed.



16. MP12.75 new dock along the LDB.



17. MP15.5 South Mill Pond no sheen observed.



18. MP15.6 LDB observed sheen and tar glob. Quantity of sheen did not warrant a sheen sweep boat.