

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, August 23, 2012

Kalamazoo River / Enbridge Spill



1. C0.4 Boat launch observed sheen and tar glob.



2. C0.4 Boat launch observed sheen and tar glob.



3. MP5.15 LDB sheen and tar globs observed.



4. MP5.15 LDB sheen and tar globs observed.



5. MP5.25 LDB sheen observed.



6. MP5.35 LDB sheen observed.



7. MP5.45 LDB sheen and tar globs observed.



8. MP5.45 LDB sheen and tar globs observed.



9. MP5.63 LDB minimal sheen observed in this location today compared to previous day's observations.



10. Ceresco Dam control point boom observed the sheen sweep boat operating along the boom.



11. MP5.55 observed a LSR poling crew.



12. MP5.0 LDB observed a LSR poling crew.



**13. MP4.5 center channel area where tar globs and sheen observed.
Quantities observed did not meet the criteria for a sweep boat.**



**14. MP4.5 center channel area where tar globs and sheen observed.
Quantities observed did not meet the criteria for a sweep boat.**



15. MP5.0 LDB sheen and tar globs observed downstream of poling crew.



16. MP5.0 LDB sheen and tar globs observed downstream of poling crew.



17. MP5.0 LDB sheen and tar globs observed downstream of poling crew.



18. MP15.5 South Mill Pond observed small ribbons of sheen flowing out of the south Mill Pond.



19. MP15.5 South Mill Pond observed small ribbons of sheen flowing out of the south Mill Pond.



20. MP21.5 observed the river bank erosion inspecting teams.



21. MP21.5 Custer Drive Bridge observed ribbons of sheen. The quantity of sheen did not meet the requirements for a sheen sweep boat.



22. MP21.5 Custer Drive Bridge observed ribbons of sheen. The quantity of sheen did not meet the requirements for a sheen sweep boat.



23. Shady Bend Campground observed conifers staged for installation of future sediment traps.



24. MP26.25 RDB no sheen observed.



25. MP26.0 RDB no sheen observed.



26. MP23.10 RDB no sheen observed.



27. MP30.8 LDB no sheen observed.



28. MP36.25 area where ribbons of sheen were observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.



29. MP36.25 area where ribbons of sheen were observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.



30. MP21.0 LDB observed a LSR poling crew.



31. Portage launch below Ceresco Dam, sheen observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.



32. Portage launch below Ceresco Dam, tar globs and sheen observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.



33. Portage launch below Ceresco Dam, tar globs and sheen observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.



34. Portage launch below Ceresco Dam, sheen observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.



35. Portage launch below Ceresco Dam, notice of river opening sign altered.



36. Ceresco Dam portage kiosk materials have been added. No decontamination station observed.