

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Thursday, August 30, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:  
Larry Rader  
START-USEPA  
Situation Unit Leader



1. Sheen and tar globules observed at the trestle above Ceresco Dam.



2. Sheen and tar globules observed within containment at Ceresco Dam.



3. Crews removing debris from the control point at Ceresco Dam.



4. Sediment trap survey crew observed above Ceresco Dam.



5. Sheen and tar globules observed in vicinity of sediment trap survey crew.



6. MP33.1 RDB, sheen and petroleum odor observed.



7. Sediment trap survey crew observed in Morrow Lake Delta.



8. Sediment trap survey crew observed in Morrow Lake Delta.



9. Crews inspecting boom and sediment curtain in Morrow Lake Delta.



10. Crews removing vegetation and debris from E4.0 control point.



11. South cove of Morrow Lake. No sheen observed.



12. Sheen sweeper boat in southern cove of Morrow Lake.