

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, August 31, 2012

Kalamazoo River / Enbridge Spill



1. MP 5.30 to MP 5.63, area where sheen was observed.



2. MP 5.35, Sheen and tar globules observed.



3. MP 5.50, sheen and tar globules observed in channel.



4. MP 5.50, sheen and tar globules observed in channel.



5. Ceresco Dam Impoundment, area where sheen and tar globules were observed.



6. Ceresco Dam Impoundment, sheen and tar globules observed within containment.



7. Ceresco Dam Impoundment, sheen and tar globules observed within containment.



8. Ceresco Dam Impoundment, sheen and tar globules observed.



9. MP 10.75 LDB, absorbant boom remains in place around undercut bank.



10. MP 10.75 LDB, silver sheen observed within containment.



11. MP 21.5, sheen observed from Custer Road Bridge.



12. MP 21.5, sheen sweeper boat operating in area.



13. Morrow Lake South Cove, no sheen observed.



14. Rowe Island, no sheen observed.



15. Morrow Lake, sheen observed around E 4.5 Boat Launch.



16. Morrow Lake, sheen observed around E 4.5 Boat Launch.



17. Morrow Lake North Cove, area where sheen was observed.



18. Morrow Lake North Cove, sheen observed.



19. Morrow Lake Delta, crew observed clearing vegetative debris from Boom C.