

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, September 04, 2012

Kalamazoo River / Enbridge Spill



1. MP 5.0 to MP 5.15 RDB, sheen observed upstream of C 0.4 Boat Launch.



2. MP 5.0 RDB, sheen observed upstream of C 0.4 Boat Launch.



3. MP 5.15 RDB, sheen and tar globules observed near C 0.4 Boat Launch.



4. MP 5.10 to MP 5.63 LDB, sheen and tar globules observed.



5. MP 5.25 LDB, sheen and tar globules observed.



6. MP 5.50 LDB, sheen and tar globules observed.



7. MP 5.50 LDB, sheen and tar globules observed.



8. MP 5.63 LDB, sheen and tar globules observed downstream of the trestle.



9. MP 5.63 LDB, sheen and tar globules observed downstream of the trestle.



10. MP 5.63 LDB, sheen and tar globules observed downstream of the trestle.



11. Ceresco Control Point, sheen and vegetative debris observed within containment.



12. Ceresco Control Point, sheen observed at control point.



13. MP 21.50 RDB, few streamers of sheen observed from Custer Bridge. No response was required.



14. Morrow Lake Delta, crews observed removing vegetative debris from control point.



15. Morrow Lake South Cove, no sheen observed.



16. Morrow Lake Rowe Island, no sheen observed.



17. Morrow Lake North Cove, few random areas of sheen observed. No response was required.



18. Morrow Lake North Cove, random sheen observed.