

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, September 14, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Sheen and tar globules observed at MP5.15 LDB.



2. Sheen and tar globules observed at MP5.20 LDB.



3. Sheen and tar globules observed at MP5.25 LDB.



4. MP5.5 LDB sheen and tar globs observed.



5. MP5.63 LDB at the railroad trestles sheen observed.



6. MP5.63 LDB below the railroad trestles sheen and tar globs observed.



7. MP5.63 LDB below the railroad trestles sheen and tar globs observed.



8. MP5.63 LDB below the railroad trestles sheen and tar globs observed.



9. MP5.63 LDB below the railroad trestles sheen and tar globs observed.




10. CSD observed above Ceresco Dam.



11. Ceresco Dam observed a crew performing boom maintenance.



12. Observed sheen and tar globs observed collecting along the Ceresco Dam control point boom.



13. MP5.55 RDB sheen and tar globs observed.



14. MP5.55 RDB sheen and tar globs observed.



15. MP5.0 – MP5.15 RDB sheen and tar globs observed.



16. MP5.0 – MP5.15 RDB sheen and tar globs observed.



17. MP28.25 Oxbow observed a crew reinstalling the CSD.




18. MP28.25 RDB sheen observed around the boat. The sediment was agitated when docking to observe the work.



19. MP28.25 RDB sheen observed around the boat. The sediment was agitated when docking to observe the work.




20. MP30.8 LDB observed a Bathymetry survey.



21. MP30.8 LDB observed a Bathymetry survey.



22. Observed the sweep boat operating between MP21.5 – MP30.8.



23. MP36.0 LDB ERO work site.



24. Morrow Lake Delta observed crews performing Bathymetry surveying.



25. Morrow Lake Delta observed crews performing Bathymetry surveying.



26. Morrow Lake Delta observed crews performing Bathymetry surveying.



27. Morrow Lake Delta observed crews performing Bathymetry surveying.



28. Morrow Lake Delta Boom F observed a crew performing boom and curtain inspection.



29. Morrow Lake south cove observed a poling crew.



30. Morrow Lake north cove a poling crew.