

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, October 1, 2012

Kalamazoo River / Enbridge Spill

Prepared by:
Larry Rader
START-USEPA
Situation Unit Leader



1. MP 5.63 RDB, no sheen observed along shoreline upstream of trestle.



2. Crews removing debris from Ceresco Dam control point.



3. Sheen observed within containment at Ceresco Dam control point.



4. Sheen and tar globules observed within containment along Ceresco Dam control point.



5. Sheen and debris observed within containment along Ceresco Dam control point.



6. Sheen observed along LDB at Ceresco Dam near upstream portage.



7. Sheen observed along LDB at Ceresco Dam near upstream portage.



8. RI crews collecting samples along LDB near MP 8.0.



9. MP 15.5 South Mill Pond RDB of river channel, no sheen observed.



10. View of culverts at MP 15.75 in North Mill Pond. No sheen observed.



11. Poling crew operating along boom B in Morrow Lake Delta.



12. Boom configuration C in Morrow Lake Delta. Sheen observed along containment boom.



13. Sheen and tar globules observed along boom C in Morrow Lake Delta.



14. Curtain inspection crew observed working along boom E2.



15. Crews removing debris from E2 control point boom in Morrow Lake Delta.



16. North cove of Morrow Lake. No sheen observed.



17. South cove of Morrow Lake, no sheen or tar globules observed.



18. Main river channel of Morrow Lake, no sheen or tar globules observed.