

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, October 8, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	46.13	48.94
Ceresco Dam Containment Boom	46.50	56.52
C3.2 Boat Launch Gauge	47.32	49.05
E4.0 Boat Launch Gauge	50.19	52.98
C5 Boat Launch Gauge	52.09	51.79

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. MP5.35 LDB, spontaneous ribbons of sheen observed along shoreline.



2. MP5.45 LDB, spontaneous sheen and tar globule observed along shoreline.



3. MP5.63 LDB no sheen observed.



4. Ceresco Dam control point observed the boom maintenance crew.



5. MP5.70 sheen observed within debris along Ceresco containment boom.
Sheen appeared to be caused from the boom maintenance boat.



6. MP5.70 sheen observed within debris along Ceresco containment boom.
Sheen appeared to be caused from the boom maintenance boat.



7. MP5.70 sheen observed within debris along Ceresco containment boom.
Sheen appeared to be caused from the boom maintenance boat.



8. MP 5.63 RDB spontaneous ribbon of sheen observed.



9. MP10.5 Sediment Trap observed a sampling crew.



10. MP10.5 Sediment Trap observed a sampling crew.



11. MP10.5 Sediment Trap observed a sampling crew.



12. MP10.75 Sediment Trap no sheen observed.



13. Morrow Lake Delta Gate E observed a crew removing debris from the boom.



14. Morrow Lake Delta Gate F observed a crew performing adjustments to the curtain.



15. Morrow Lake Delta Gate C no sheen observed.



16. Morrow Lake Delta Gate B no sheen observed.



17. MP36.5 LDB 35th Street Bridge sheen observed when the boat reversed from the gage.



18. MP36.5 LDB 35th Street Bridge sheen observed when the boat reversed from the gage.



19. MP34.5 LDB background sampling crew observed.



20. MP34.5 LDB background sampling crew observed.



21. MP15.5 South Mill Pond no sheen observed.



22. MP15.6 LDB spontaneous ribbon of sheen observed.