

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Tuesday, October 9, 2012

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

| Location                     | Water Temp. (°F) | Sediment Temp. (°F) |
|------------------------------|------------------|---------------------|
| C0.4 Boat Launch Gauge       | 46.97            | 49.42               |
| Ceresco Dam Containment Boom | 47.14            | 55.04               |
| D2 Boat Launch Gauge         | 50.58            | 51.77               |
| E4.0 Boat Launch Gauge       | 52.57            | 53.43               |
| C5 Boat Launch Gauge         | 50.51            | 50.66               |

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. MP5.35 LDB, spontaneous ribbons of sheen observed along shoreline.



2. MP5.35 LDB, spontaneous sheen and tar globule observed along shoreline.



3. MP5.45 LDB, spontaneous sheen and tar globule observed along shoreline.



4. MP5.55 LDB, spontaneous sheen and tar globule observed along shoreline.



5. MP5.63 LDB no sheen observed.



6. Ceresco Dam Control Point observed the boom maintenance crew operating.



7. MP5.70 sheen observed within debris along Ceresco containment boom.



8. MP5.70 sheen observed within debris along Ceresco containment boom.



9. MP5.70 sheen observed within debris along Ceresco containment boom.



10. MP5.55 RDB spontaneous sheen observed.



11. MP19.25 Sediment Trap observed a sampling crew.



12. MP19.25 Sediment Trap observed a sampling crew.



13. MP19.25 Sediment Trap observed a sampling crew.



14. MP19.25 Sediment Trap observed a sampling crew.



15. MP13.5 Overbank background sampling crew observed.



16. MP15.5 South Mill Pond no sheen observed.



**17. MP15.55 LDB sheen observed, quantity of sheen would not warrant a sweep boat.**



**18. Morrow Lake South Cove.**



**19. Morrow Lake South Cove sheen observed quantity of sheen would not warrant a sweep boat.**



**20. Morrow Lake Delta sheen observed along Gate E.**



**21. Morrow Lake Delta Gate C observed a crew performing curtain maintenance.**



**22. Morrow Lake Delta Gate B.**



23. MP36.25 sheen observed, quantity of sheen would not warrant a sweep boat.



24. MP36.25 sheen observed, quantity of sheen would not warrant a sweep boat.