

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, October 16, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	49.95	51.00
Ceresco Dam Control Point Boom	49.19	54.10
C3.2 Boat Launch Gauge	49.82	51.70
C5 Boat Launch Gauge	49.86	50.66
E4 Boat Launch Gauge	53.51	53.05

US EPA ARCHIVE DOCUMENT


Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. MP5.35 ribbons of sheen and tar globs were observed.



2. MP5.45 RDB sheen and tar globs were observed.



3. Ceresco Dam Control Point Boom observed a crew removing debris from the boom.



4. Ceresco Dam Control Point Boom observed sheen collecting along the boom.



5. Ceresco Dam Control Point Boom observed sheen and tar globs when the boat reversed away from the boom.



6. Ceresco Dam Control Point Boom observed sheen and tar globs when the boat reversed away from the boom.



7. MP4.5 Area where we removed a navigational hazard from the river and generated sheen.



8. MP4.5 sheen generated by the boat while removing a navigational hazard from the river.



9. MP4.5 sheen generated by the boat while removing a navigational hazard from the river.



10. MP4.5 navigational hazard removed from the river.



11. MP8.75 R1 while inspecting the area the boat agitated the sediment and sheen was observed.



12. MP8.75 R1 while inspecting the area the boat agitated the sediment and sheen was observed.




13. MP8.75 R1 while inspecting the area the boat agitated the sediment and sheen was observed.



14. MP15.0 LDB sheen observed around the island.



15. MP15.0 LDB sheen observed around the island.



16. Morrow Lake Delta observed the CSD sampling crew.



17. Morrow Lake Delta observed the CSD sampling crew.



18. Morrow Lake Delta Gate E observed a crew removing debris from the boom.



19. Morrow Lake observed the sweep boat operating.



20. Morrow Lake south cove ribbons of sheen observed. Quantity of sheen did not require a sweep boat.



21. Morrow Lake Delta Gate E.



22. Morrow Lake Delta Gate E sheen and tar globs observed collecting along the boom.



23. MP36.25 LDB sheen was observed. The quantity of sheen did not warrant a sweep boat.



24. MP36.25 LDB sheen was observed. The quantity of sheen did not warrant a sweep boat.



25. MP36.25 LDB sheen was observed. The quantity of sheen did not warrant a sweep boat.



26. MP36.25 LDB sheen was observed. The quantity of sheen did not warrant a sweep boat.